

HAGEDORN, INC.

"SUITE B"

1924 BDWY. Vancouver, Wash.

Ph. (206) 696-4428

LAND SURVEYORS

Subdivisions, Boundaries, Control, Topography,
Construction Surveys, & Road Layout

Skamania

County

Corner Code No. C-21

T. 1 N. R. 5E W.M.

Segregated Surveys

Name Quarter corner common to Sections 1 & 2

Corner No.

94025

DLC, HFS, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite

1. History of Corner Establishment and Subsequent Restoration:

Wood post originally set by "Van Fleet and Newsome" in 1860, from which a Fir 30" bears South 68° West 48.2 feet (73 links) and a 30 inch Fir bears South 70° East 34.3 feet (52 links). This corner was set on a true line running South from the North boundary of the Township and a call was made at the corner for "commence ascending". I found the Section 2 BT with scribing visible on upper blaze "4" and axe marks on lower blaze (both blazes being burned). This BT is an uproot stump lying on its side (pointing Southerly). At first glance, it appears that the uproot was pushed down to its present position by a cat (area was logged in approximately 1940). Upon closer inspection, I noticed that the inverted roots are not weathered as are other blowdown trees, indicating that the stump has only tipped over in the last year or two. It is lying on top of the "shell" of a down log which has rotted away, allowing the BT to fall over recently. I also found rotted wood in the ground under the exposed roots, indicating that it had been attached at this point. If you were to stand the uprooted stump back up, the scribed face would bear exactly as called for in the GLO notes and the corner position is immediately at the base of a 150 foot high knoll to the South (matching the "commence ascending" call). I could not locate the other BT called for. Approximately North 70° West, 5 links (GLO: South 70° East, 52 links) would be the position of the only other tree of the appropriate age and size in the area. This tree is also an uproot, tree length that has broken and rolled slightly upon impact or during logging. I can find no axe marks on it at all. A corner position at record bearing and distance from this tree would be up on the South slope among a group of stumps that may have been young trees at the time of the original survey. This location does not fit the call for ascent by about a chain. I discard this point as unsatisfactory and set 5/8 inch iron rod at record bearing and distance from the Section 2 BT.

RPS: 24" Fir South 45° West 22.26 feet
12" Alder East 23.80 feet
8" Alder North 52° West 16.06 feet.

Note: Post in rock pile and 1962 DNR tags (immediately above logging road)
188 feet North 03° West of true quarter corner.

Washington Plane Coordinates: Zone, Y X
Order Accuracy, Derived From:

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 4-20-82

Signature

12412
Certificate No.

AUDITOR'S CERTIFICATE

Filed for record this 27th day of May 1982 at 3:00 P. M. In Book 175 of 175 at page 17 at the request of

X

County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.