

93077

INTERNATIONAL PAPER CO.

ENGINEERING OFFICE

P. O. BOX 67 - AMBOY, WASHINGTON 98601 - PHONE (206) 247-5411

LAND CORNER RECORD

Skamania

County

Z-13

T. 9 N. R. 6E W.M.

Corner Code No.

Segregated Surveys:

Name: Section Corner 33-34

Corner No.

DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

Corner established in 1903. Post and two BT's.

2. Description of Evidence Found:

Found 1" iron pipe and 10" "Larch" (Pacific silver fir) BT with visible scribe. BT is blown down. Could not find other BT. Origin of iron pipe is unknown.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's field Book No. Page No.

Date of work 8/81

Set 2" x 30" galvanized iron pipe with brass cap stamped:



Re-referenced as follows:

16" Silver fir stump BRS East 26.2', scribed "RP S34".

36" Hemlock BRS N54W 47.5' scribed "RP S33".

Distances to nail, RPs tagged.


Washington Plane Coordinates: N/A Zone, Y X

Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date Sept 15, 1981

Signature Frank M. PumphreyL.S. 15669
Certificate No.

93077

AUDITOR'S CERTIFICATE

Filed for record this 15th day of September 1981 at 1:30 P M.
In Book 7/6 of Proprietary at page 4 at the request
of John Thayer for International Paper Co.

Seal Messenger by B. Baker
County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.

PUBLISHED P.T.S. 10-7-78