

93482

RES 20-1808(9-77)

4/7 PAGE 4

LAND CORNER RECORD

T. N. R. 21 W.M. Skamania County
 Segregated Surveys: Corner Code No. 1-13
 Name: Section Corner Corner No.:
 (DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite)

1. History of Corner Establishment and Subsequent Restoration:

Corner established in July or Aug. 1895 by Deputy Jacob Richardson under his contract No. 457.

Marked orig. 4" Yew post.

20" Hemlock N28E 36 lks..

18" Hemlock S52E 13 lks..

15" Hemlock S63W 10 lks..

8" Hemlock N25W 46 lks..

2. Description of Evidence Found:

U.S.F.S. 2" Brass cap on 2" iron pipe 6" above ground.

Orig. 15" now 32" Hemlock S60W 7.2 ft. scribing visible.

Orig. 18" now 30" Hemlock windfall-stood S52E 8.6 ft. headed blaze.

Orig. 8" now 16" Hemlock N22W 29.5 ft. scribe marks visible.

There is no evidence of the Northeast BT at record bearing and distance.

See Wind River Experimental Forest Timber Survey Report-1933 corner listed as set from original evidence.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 3 Page No. 9 Date of work Oct. 1981

Set guard post South with sign 54-4 only.

Nailed 54-4 and BT signs to all BT's and painted band and blazes red.

New Bearing Trees:

2" D-Fir N10E, 29.0 ft. scribed T4NR78322 upper blaze and a lower blaze scribed BT and with a

3/4" Brass disk stamped PLS 16337.

12" Hemlock S25E, 60.9 ft. scribed T4NR78322 upper blaze and a lower blaze scribed BT and with a

3/4" Brass disk stamped PLS 16337.

Washington Plane Coordinates: Zone Y X

Order Accuracy: Derived From:

Pin Pointed on Photo No. Date Located at:

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 11/15/81

Signature [Signature] Certificate No. 76227

AUDITOR'S CERTIFICATE

Filed for record this 18th day of December 1981 at 2:35 AM. In Book 47 of Monuments at page 4 at the request of Bishop Surveying, Inc.

J. M. Olson
 County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.