

LAND CORNER RECORD

T. 4 N. R. 7 W. M. Skamania County
 Segregated Surveys: Corner Code No. V-17
 Name: Section Corner Corner No.:
 D.L.C. HES. Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration

Corner established in July or Aug. 1895 by Deputy Jacob Richardson under contract No. 457.

Marked orig. 4" Yew post.

6" Hemlock N70E 50 lks..

5" Maple S42E 20 lks..

10" Hemlock S65W 32 lks..

12" Hemlock N23W 58 lks..

2. Description of Evidence Found:

3/4" Iron pipe set in concrete.

No BT's or stumps in area tha match G.L.O. callc.

Adjacent landowner states that corner was set in the 1930's by the C.C.C.. It was probably set at the existing fence corner, possibly from the original BT's.

Accepted as the available evidence remaining today.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 3 Page No. 5 Date of work Oct. 1981

Set 2 1/2"x30" Gal. steel pipe with a 2 1/4" Brass cap in place of pipe in concrete.

Set guard posts North and West with sign 54-4 and BN 102 decal.

Marked:

Nailed 54-4 and BT signs to BT's and painted band and blazes red.

T4N R7E

S27 S26

S34 S35

1981

PLS 16337

New Bearing Trees:

20" D-Fir N28E, 7.9 ft. scribed T4NR7ES26

upper blaze and a lower blaze scribed BT

and with a 3/4" Brass disk stamped PLS 16337.

16" D-Fir S20E, 69.2 ft. scribed T4NR7ES35

upper blaze and a lower blaze scribed BT

and with a Brass disk stamped PLS 16337.

14" D-Fir S10W, 32.3 ft. scribed T4NR7ES34

upper blaze and a lower blaze scribed BT

and with a 3/4" Brass disk stamped PLS 16337.

12" D-Fir N24W, 40.7 ft. scribed T4NR7ES27

upper blaze and a lower blaze scribed BT

and with a 3/4" Brass disk stamped PLS 16337.

Buried pipe in concrete
in hole next to monument set.

Washington Plane Coordinates: Zone, Y, X

Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 11/17/81

Signature Larry D. Bishop

Certificate No. 16227

Registered



AUDITOR'S CERTIFICATE

Filed for record this 18th day of December 1981 at 10:45 A.M. in Book 4/7 of Monuments at page 23 at the request of

Bishop Surveying Inc.

County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Laws of 1973.