

LAND CORNER RECORD

T. 4 N, R. 7E, W.M. Skamania County
 Segregated Surveys: Corner Code No. V-13
 Name: Section Corner Corner No.:
 D.C., H.E.S., Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite

1. History of Corner Establishment and Subsequent Restoration:

Corner established in July or Aug. 1895 by Deputy Jacob Richardson under his contract No. 457.

Marked orig. 4" Yew post.
 40" Fir N20E 31 lks..
 6" Yew S70E 24 lks..
 4" Maple S40W 25 lks..
 40" Fir W75W 21 lks..

2. Description of Evidence Found:

U.S.F.S. 2 1/2" Brass cap on a 1" Iron pipe set by U.S. Dept. of Agriculture.
 Location fits original call of top of ridge at 76.00 ch. on South line of Section.
 Corner in R/W of road. Orig. BT's most likely destroyed by road construction.
 See Wind River Experimental Forest Timber Survey Report-1933 corner listed as set from original evidence.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record, Surveyor's Field Book No. 3, Page No. 8, Date of work Oct. 1981

Set guard post Northeast with sign 54-4 only.
 Nailed 54-4 and BT signs to all BT's and painted redband and blazes red.
 New Bearing Trees:

20" D-Fir N80E, 29.3 ft. scribed T4NR7ES27 upper blaze and a lower blaze
 scribed BT and with a 3/4" Brass disk stamped PLS 10337.
 20" D-Fir S45E, 31.1 ft. scribed T4NR7ES34 upper blaze and a lower blaze
 scribed BT and with a 3/4" Brass disk stamped PLS 10337.
 16" D-Fir S60W, 37.2 ft. scribed T4NR7ES33 upper blaze and a lower blaze
 scribed BT and with a 3/4" Brass disk stamped PLS 10337.
 23" D-Fir N75W, 57.3 ft. scribed T4NR7ES28 upper blaze and a lower blaze
 scribed BT and with a 3/4" Brass disk stamped PLS 10337.

Washington Plane Coordinates: Zone, Y, X
 Order Accuracy. Derived From:
 Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 11/15/81

Signature *Lucy D. Bishop*

Registered *16337*

Certificate No.

AUDITOR'S CERTIFICATE

Filed for record this 10th day of December 1981 at 11:06 A.M. In
 Book 47 of Monuments at page 27 at the request of
Bishop Surveying Inc.
J. M. Olson

County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.

