

## LAND CORNER RECORD

Skamania

County

T. 7 N. R. 6E W.M.

Corner Code No. N-13

Segregated Surveys:

Name: Section Corner

Corner No.:

DLC, RES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

### 1. History of Corner Establishment and Subsequent Restoration:

This corner was originally set by Deputy Lewis D.W. Shelton in July 1899, Oct.-Dec. 1900 under Contract No. 552.

Set Cedar post.

Scribed 12" Fir N50 $\frac{1}{2}$ E-19 lks..

10" Cedar S12 $\frac{1}{2}$ E-22 lks..

14" Fir S82 $\frac{3}{4}$ W-16 lks..

16" Fir N21 $\frac{1}{2}$ W-2 $\frac{1}{2}$  lks..

Remonumented by Floyd A. Brooks, Cadastral Surveyor in Oct. & Nov.

Set Iron post with Brass cap.

Scribed 9" Wh. Fir N68 $\frac{1}{2}$ E-26 lks..

16" Fir S6E-29 lks..

10" Hemlock N75 $\frac{1}{2}$ W-67 lks..

### 2. Description of Evidence Found:

BLM 2 $\frac{1}{2}$ " Iron post with Brass cap.

Orig. 12" now 16" D-Fir snag N50 $\frac{1}{2}$ E-19 lks. scribing visible on opened blaze.

Orig. 10" now 2 $\frac{1}{2}$ " Cedar S12 $\frac{1}{2}$ E-22 lks. opened blaze.

Orig. 14" now 2 $\frac{1}{2}$ " uprooted sawed stump stood S82 $\frac{3}{4}$ W-16 lks. healed blaze.

Orig. 16" now 16" rotted stump N21 $\frac{1}{2}$ W-2 $\frac{1}{2}$  lks..

Brooks 9" now 11" down Wh. Fir snag stood N68 $\frac{1}{2}$ E-26 lks. healed blaze.

Brooks 16" now 18" D-Fir S6E-29 lks. healed blaze.

### 3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record, Surveyor's Field Book No. 2. Page No. 12 Date of work June 1982

#### New Bearing Trees:

9" Hemlock N26W, 30.2 ft. scribed TNR6ES16 upper blaze and a lower blaze scribed BT and with a 3/4" Brass disk stamped PLS 16337.

9" Hemlock N3E, 31.0 ft. scribed TNR6ES15 upper blaze and a lower blaze scribed BT and with a 3/4" Brass disk stamped PLS 16337.

Set guard posts East and South with sign 54-1 and BM 102 Secal.

Nailed 54-4 and BT signs to BT's and painted band and blazes red.

Washington Plane Coordinates: Zone Y X

Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at

### SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date

Signature Larry D. Bishop

16337  
Certificate No.

### AUDITOR'S CERTIFICATE

Filed for record this 13th day of JULY 1982 at 12:05 P.M. In Book 7/6 of MINNULINIS at page 13 at the request of

BISHOP SURVEYING INC

J.M. Alton

County Auditor