



SECTION 12, T6N, R6E, W.M.  
SUPPLEMENTAL SHEET

NOTE:  
THIS PLAT SUPERCEDES PLAT FILED  
UNDER AUDITORS FILE NO. 93062 VOL. 2 PG.  
25 AND 26, RECORDS OF SKAMANIA CO. WASH.

N.W. Corner, Section 12

No Corner monument found, destroyed by  
road construction.  
Found 2 O.B.T.'s

Set 2 1/2" X 30" pipe 26" in ground with  
2 1/2" brass cap marked:

S11 S12  
1981  
LS 15652

Scribed New B.T.'s

25" Fir N07°W 16.67'

Scribed T6N R6E S2 RT 54-3 & 54-3 signs

Witness object

3' X 2' X 2' stone W/PK nail in top  
S25 1/2°W 15.52'

Field Book #151, page 9

West Quarter Corner, Section 12

Found G.L.O. Monument  
2 O.B.T.'s

South One-Sixteenth Corner, Section 12

No Corner Monument Found  
No Bearing Trees Found

Set 2 1/2" X 30" pipe with brass cap marked:

S 1/16  
16N R6E  
S11 S12  
1981  
LS 15652

Scribed New B.T.'s

29" Fir N60°E 18.60'

Scribed S1/16 S12 RT 54-3 & 54-4 signs

36" Fir S31°E 46.29'

Scribed S1/16 S12 RT

Field Book #151, page 13

S.W. Corner, Section 4

Found G.L.O. Monument  
Found 6 B.T.'s

North Quarter Corner, Section 12

Found G.L.O. Monument  
2 O.B.T.'s

Witness Corner #1 for Center, Section 12

No Corner Monument Found  
No Bearing Trees Found

Set 2 1/2" X 30" pipe 26" in ground with 2 1/2" brass  
cap marked:

S11 S12  
1981  
LS 15652

Reference Monuments

Set 3/4" X 30" Rebar w/plastic cap LS 15652  
N45°E 19.92' 1 notch in cap  
S63°E 7.26' 2 notches in cap

Guard Stakes with appropriate signs attached  
behind Rebar Facing Corner 54-3 & 54-9 signs

Field Book #151, page 16

Witness Corner #2 for Center, Section 12

No Corner Monument Found  
No Bearing Trees Found

Set 2 1/2" X 30" pipe 26" in ground with 2 1/2" brass  
cap marked:

S 1/16  
16N R6E  
S11 S12  
1981  
LS 15652

Reference Monuments

Set 3/4" X 30" Rebar w/plastic cap LS 15652  
N52°W 8.21' 4 notches in cap  
S10°W 9.11' 3 notches in cap

Guard Stakes with appropriate signs attached  
behind Rebar Facing Corner 54-3 & 54-9 signs

Field Book #151, page 17

Center South One-Sixteenth Corner, Section 12

No Corner Monument Found  
No Bearing Trees Found

Set 2 1/2" X 30" pipe with 2 3/4" brass cap marked:

S1/16 S12  
1981  
LS 15652

Scribed New B.T.'s

23" Fir S15°E 52.32' scribed CS1/16 S12 RT

38" Fir S60°W 33.59' scribed CS1/16 S12 RT

54-3 & 54-4 signs

Field Book #151, page 15

South Quarter Corner, Section 12

Found B.L.M. Monument  
2 O.B.T.'s

N.E. Corner, Section 12

No Corner Monument Found, destroyed by slide  
Found 2 O.B.T.'s

Set 2 1/2" X 30" pipe 26" in ground with 2 1/2" brass cap  
marked:

S11 S12  
1981  
LS 15652

54-3 & 54-4 signs placed on B.T.'s

Field Book #151, page 5

Witness Corner for East Quarter Corner, Section 12

Found B.L.M. Monument  
Found 2 O.B.T.'s

South One-Sixteenth Corner, Section 12

No Corner Monument Found  
No Bearing Trees Found

Set 2 1/2" X 30" pipe 26" in ground with 2 3/4" brass cap  
marked:

S 1/16  
S12  
1981  
LS 15652

Scribed New B.T.'s

27" Fir South 13.50' scribed S1/16 S12 RT

13" Fir N14W 12.82' scribed S1/16 S12 RT

Field Book #151, page 14

S.E. Corner, Section 12

Found B.L.M. Monument  
Found 2 O.B.T.'s

NOTE: HORIZONTAL DISTANCES TAKEN FROM MONUMENT TO BRASS  
TAGS (LS15652) NAILED IN TOP CIRCLE OF NEWLY SCRIBED "B"

CERTIFICATE NO. \_\_\_\_\_

AUDITOR'S CERTIFICATE

FILED FOR RECORD THIS 30TH DAY OF JULY 1982 AT  
10:31 A.M. IN BOOK 2 OF SURVEYS AT PAGE 73 AT  
THE REQUEST OF MIKE HOBBS & ASSOCIATES, INC.

J.M. Olson by d. Davis, C.P.  
COUNTY AUDITOR

SURVEYOR'S CERTIFICATE

THIS MAP CORRECTLY REPRESENTS A SURVEY MADE BY  
ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE  
REQUIREMENTS OF THE SURVEY RECORDING ACT AT THE  
REQUEST OF U.S. FOREST SERVICE, DEPT. OF AGRICUL-  
TURE, IN JUNE, 1981.

Michael H. Hobbs  
LICENSE NO. 15652

MIKE HOBBS & ASSOCIATES, INC.

475 NW CHEHALIS AVENUE

P.O. BOX 149 (206) 748-8803  
CHEHALIS, WASHINGTON

DRN 78 DATE 7-29-81

CHKD BY Job NO. 81-51

SCALE — SHEET 2 OF 2