LAWSON LAND SURVEYING

(206) 256-8008

JOEN G. LAWSÓN Regulaterá Proteisional Lind Sulváyer Regustered Professional Engineer Y-Plaza 14612-A 4th Plain Rd. Vancouver, WA 98662 LAND CORNER RECORD

T 3 N, R 8 E , W.M.; Skamania County

Corner Code Number: N-19

Page 1 of 1

Corner

Name: One-quarter Corner common to Sections 14 and 23 : Number N-19
DLC, HES Mining Claim, Indian Allotment, Federal Reserve, Townsite

1. History of Corner Establishment and Subsequent Restoration; description of Evidence Found:

Today there is no evidence of the original bearing trees. In 1952, Bonneville Power Administration found a stake in a North-South and East fence corner. According to Louis Larson who was born and raised near here, and who still lives on part of the old Larson homestead, this has always been the corner. He said there was an old homesteader's cabin just a short distance from this corner. This area did not burn until 1915, so with the early settlement in this area, in all likelihood, this is a perpetuation of the original corner. Also, there are a couple old surveys around 1910 that tie to this corner. One is Road Book 4, Page 113, Skamania County. I also searched for this corner in 1968.

2. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location.
Diagram corner and indicate meridian and reference to map of record.

LAWSON LAND SURVEYING Job: # 25 - 82 - 150308 : Date of Work: June, 1982

Found a 3/4-inch diameter Iron Pipe, with Olson cap, 3 feet long.



Washington Plane Coordinates: Zone, Y Order of Accuracy Derived from:			· · · · · · · · · · · · · · · · · · ·
Order of Accuracy. Der ived in om.			
Pin Pointed on Photo No. Date	Located at	2 1	
SURVEYOR'S CERTIFICATE		H G. LAW	i V
This corner record correctly represents work perform by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.	med ST	O St WASHING O	OK.
Signature 6. Lawson Date Oct 1982		SI PEGIETERED P	
Certificate Number 11989		BOOMAL LAND	7
AUDITOR'S CERTIFICATION AND AUDITOR'S CERTIFICATION AUDITOR'S AUDITO		45 co	P.M.
in book 3/8 of MONUMENTS at Page of IAWSON LAND SURVEYING			
OI THOSON FIND SURVEYING			