

STATE OF WASHINGTON
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS

BOOK 4/7 PAGE 94

LAND CORNER RECORD

T. 4 N, R. 7 East, W.M.

Skamania

County

Segregated Surveys:

Corner Code No. Z-23

Name: Recinds L.C.R. # 96790, dated 1 December 1983

Corner No.: n/a

DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:


Originally set by G.L.O. surveyor, Jacob Richardson, during 1895 G.L.O. survey.
In 1903, this corner was found by G.L.O. surveyor, Robert F. Whitham during Retracement survey.
In 1983, the Dept. of Natural Resources set a D.N.R. concrete monument with stamped brass cap at single-proportioned corner position.

2. Description of Evidence Found:

Above described D.N.R. concrete monument with stamped brass cap.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.24 Page No. 52 Date of work 9-25-'84

Reset found D.N.R. concrete monument to newly calculated single-proportioned corner position based on reset northeast corner of Section 1 T.3 N., R.7 E., W.M.
Date restamped on brass cap '1984'.
Corner shown on D.N.R. Final Map # 477.
See corner diagram on reverse side.



Washington Plane Coordinates: South Zone, Y 166,151.64, X 1,645,501.36
3rd Order Accuracy. Derived From: Ties to USC & GS Control Stations
'Greenleaf' and 'Sedum Point'.

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date Jan 15, 1985

Signature M. A. Kinnaman

11977

Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this 21st day of JANUARY 1985 at 12:00 P.M. In Book 47 of MONUMENTS at page 14 at the request of Washington State Department of Natural Resources.

M. A. Kinnaman
County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.

GIO of 1895

West 40.00 set post
6" fir N4W 30L
4" fir S35E 10L

South 1/4 corner, Section 36 T4N R7E

No GIO evidence found

Calc. position falls in a 36" fir stub.

Set RM's as shown.

Both RM's are on the section line

9-25-84

Gordon
Grossler
Hanlin

52
600.14

