


99046



WEYERHAEUSER COMPANY

BOOK 10/5

PAGE 57

LONGVIEW AREA

LAND CORNER RECORD

19120
36129

SKAMANIA

County

Corner Code No. R-5

T 10 N. R. SE W.M.
Segregated Surveys:

Name

Corner No.

DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite

1. History of Corner Establishment and Subsequent Restoration: GLO CORNER FOUND IN 1940 BY MAPPING CREW. WE FOUND REMAINS OF POST w/scr. bc - NOT ORIGINAL - AND 1 BT WITH HEALED FACE. RESET 2 1/2" ALUMINUM MAGNETIZED PIPE WITH CAP AT POST POSITION.

2. Description of Evidence Found: Remains of Post with Scribing. Not ORIGINAL.

48" FIR STUB N43E 18.94 TOCTR. HEALED FACE. STUB 25' HIGH.

GLO 36" FIR: N44 1/2 E 28 LKS 18.48'

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 1-84 Page No. 3 Date of work 7-26-84



☐ REFERENCE PLATE

☐ USFS SIGN S4-9

0 1/4 x 2 1/4 GALVANIZED NAIL

SEE SURVEY

Vol 2 P 173



CAPAS STAMPED

Washington Plane Coordinates: Zone, Y, X

Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at:

SURVEYOR'S CERTIFICATE

[SEAL]

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 1-25-85

Signature

Certificate No. LS16196

AUDITOR'S CERTIFICATE

Filed for record this 29th day of MARCH 1985 at 11:10 AM. In Book 10/5 of MONUMENTS at page 57 at the request of

WEYERHAEUSER COMPANY, LONGVIEW

W. M. Olson, Jr. d. J. New Dep

County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.