

99326

State of Washington
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

1/4 31
6

Skamania County :

T 8 N, R 5 E, W.M.

Corner Code No. Z-3

Segregated Surveys:

Name: N/A

Corner Number: N/A

1. History of Corner Establishment and Subsequent Restoration: Originally set by GLO in 1900. Subsequently restored incorrectly by DNR in 1964 with a concrete monument. Properly restored in 1981 by LS 15652, Mike Hobbs, with a 2 1/2" pipe with brass cap.

2. Description of Evidence Found:

- 2 1/2" pipe with brass cap.
- 38" silver fir BT stump with visible scribe at N18W 12.54 feet to center.
- 30" silver fir BT stump at S20W 15.18 feet to center.
- 5" hemlock, scribed, at N62E 13.66 feet (1981 "BT").
- DNR concrete monument at S60E 2.83 feet from pipe.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 601.06C, Page No. 57. Date of work 5-28-85.

Removed DNR concrete monument.

See corner diagram on reverse side.




Washington Plane Coordinates: South Zone, Y _____, X _____ Third
Order Accuracy.
Derived from: _____
Pin Pointed on Photo No. _____, Date _____, Located at _____

SURVEYOR'S CERTIFICATE

[Seal]

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date May 29, 1985.

H. Thomas Laird Jr. 21490
Signature Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this 21st day of MAY 1985 at 1:15 P.M.
In Book 8/5 of MONUMENTS at page 1-2 at the request
of Washington State Department of Natural Resources.

Registered S
Indexed S
Indirect S
Filed _____
Mailed _____

Wm. Olson County Auditor

GIC survey of 1900
 38.00 Set a post
 30' White Fir NW 18W 19L 12.54'
 21' White Fir S 20 1/2 W 23 L 15.18'

1/4 corner $\frac{31}{4}$ T 7 1/2 8 N R 5 E, w. 1/4

Found 2 1/2" pipe w/ brass cap, 2 BT stumps,
 one of which has scribbles, 1 newly set dot
 BT (not equal).

Also found 4 1/4" DNR conc. mon. at S 10 E
 7.83 feet from pipe. Mon. was set in
 1904 by intersection of 610 distance from the
 face of the BT's. Using this method the
 bearings set in.

The pipe was set by intersecting 610 distance
 from the BT centers. Using this method the
 bearings fit.

Accepted the pipe as the corner and
 removed the DNR conc. mon.

L. M. B. B. B.

5-25-85
 Land
 Mark
 601-06C

57
 RSE
 TBM
 Y4 5 31-SC
 7781
 1881
 1881

