

100801

State of Washington
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

Skamania County

T 7 N, R 5 E, W.M.

Corner Code No. V-5

Segregated Surveys:

Name:

Corner Number:

1. History of Corner Establishment and Subsequent Restoration: Originally set by GLO in 1900. Subsequently restored with a DNR concrete monument in 1967 and later with a 5/8-inch rebar with plastic cap; LS 15669, date unknown.

Corner monumentation destroyed by fire trail construction.

2. Description of Evidence Found:

Portions of DNR concrete monument laying on ground.

5/8" rebar with plastic cap laying on ground.

13" fir stump BT at N51W, 17.16 feet from monument, with chunk of scribing at base.


13" fir stump BT at N33E, 18.51 feet from monument, not cut out.

18" fir stump BT at S39W, 20.44 feet from monument, not cut out.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 601:07, Page No. 56. Date of work 3-3-86.

Set DNR aluminum monument, with magnetic breakaway plastic base, from the centers of 3 BT stumps.

See diagram on reverse side.



Registered	
Indexed, Dir.	
Indirect	
Filmed	
Mailed	

SURVEYOR'S CERTIFICATE


[Seal]

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.
Date: March 6, 1986

H. Thomas Laird Jr.
Signature

21490

Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this 6 day of March 1986 at 1:07 P.M.
In Book 7/5 of Monuments at page 78 at the request
of Washington State Department of Natural Resources.

Gary M. Albright
County Auditor

07-9 Survey of 1900
0031

520 - 40 00.02 - Lot printed 14x10x7

with 1 notch on S and 5 on E, 11

— 2007-2008 period

10.11.2021 14:27

72/122 3/4/55 11/12

2811 5292 316

792 262

42

127

10

675

SECTION CORNER 30/29 31/32 T7N R5E

Found 3 BT stamps, 1 of which had scribbling on the ground next to it. The other 2 had not been used.

Found DWE core mon all broken up and
laying on top of ground.

Found 5/3 robin with plastic cap laying
on ground. (LS 15669 - Frank Humphrey)


Corner monumentation destroyed by
construction of fire trail around
clearcut unit.

78-3-86

LAIRO

۲۴
 ۲۵
 ۲۶

77W
550 512
531 532
255
1986



Measurements are to
4" spiles driven into
the centers of the
stumps.

Set 2 3/8" aluminum pipe w/ 3/4" alum cap
flush w/ ground. Pipe has a negative
breakaway plastic base.

Do suitable live trees within a convenient distance

recurrent set from centers of BTCs.

CCR filed 2/2/27