

FILED FOR RECORD

EXAMINED BY

BY

JUL 7 12:39 PM '87

103452

AUDITOR

GARY M. OLSON

BOOK 4/9 PAGE 66

T. N. TRANTOW SURVEYING

412 W. Jefferson P.O. Box 287

Bingen, Washington 98605 (509) 493-3111

LAND CORNER RECORD

T 4 N, R 9E, W.M. SKAMANIA County Corner Code No. N-15

Name: 1/4 corner common to Sections 15 & 22 Corner No.:
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration: 2. Description of Evidence Found:

GLO in 1892 set a post for this corner, from which bear:

6" fir, S52E, 15 links (9.90 ft.)

10" fir, N27E, 22 links (14.52 ft.)

Pipe set by Broughton Lumber Co. for corner circa 1946.

LS 16337 in 1984 rejected pipe and established corner by single proportion.

2. Found iron pipe

Found remains of rotted windthrow, burned, but with healed scars which may indicate the remains of a face. Position of tree fits call to pipe, but poorly.

Found remains of a rotted & burned squared post, about 14" long & 4 1/2" square, tied with flagging and lying approx 3' East of pipe. Available records only indicate this pipe was set at least c. 1960, but no mention made of post. It is possible that post was found and replaced with pipe, as water table is only one foot below the surface in this swampy area. Post has been burned by the 1939 fire which went through this area, which predates any USFS work. The one degree bend in the section line at this corner is opposite, but identical to that noted at the North edge of Sec.15 and the South edge of Sec.23.

Also found remains of a 2x2x30" 'poke' lying near corner, perhaps 20 yrs. old.

I accept the pipe as the corner and reject the proportional position.

I replaced the iron pipe with a new monument

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record.

F.B. No. 40922 Page No. 7 Job No. 87325 Date of Work 15 April 1987

Replaced iron pipe with 1 1/2x30" galvanized iron pipe with 2 1/2" brass cap, 22" in the ground, from which bear:

12" D-fir position, S30E, 6.9 ft.

6" D-fir, N01W, 15.00 ft. to center of tree scribed on North side, 1/4S22BT

Iron pipe for proportioned 1/4 corner, N01W, 46.19 ft.

7" cottonwood, S66W, 28.13 ft. to nail in side @ center of tree scribed S22WT

22" WRC cut stump, S30E, 19.18 ft. to nail in side @ center of stump

Latter two WT's are marked with aluminum tags

Washington Plane Coordinates: South Zone, Y 181813.81, X 1714603.23
THIRD Order Accuracy. Derived From: 1977 DNR SURVEY IN S.23,
T4N R9E.

Pin Pointed on Photo No. NA Symbol Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.

Signature

Date 30 May 1987

Certificate No. 15673

AUDITOR'S CERTIFICATE

Filed for record this day of 19 at M. In S
Book of at page at the request of Index

T. N. TRANTOW SURVEYING

County Auditor

Indirect

Filed

Mail