

LAND CORNER RECORD

T 4 N, R 7E, W.M. Skamania County
Segregated Surveys: Corner Code No. Z-9
Name: Section Corner No.:
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

This corner was originally set by Deputy Robert F. Whitham in 1903 under Contract No. 600.

Set Maple post
7" Dogwood N76½E-68 lks.
30" Fir N55½W-11 lks.

2. Description of Evidence Found:

DNR concrete monument with 3" Brass cap stamped:
Orig. 30" now 50" D-Fir snag N55½W-7.3' burned
rotted blaze.

Orig. NE BT gone.
Now 45" D-Fir stump S22E-43.3' with DNR tag.
Now 26" D-Fir stump S75W-24.4' with DNR tag.

T4N R7E
S32 S33
1969
JCL

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 2 Page No. 2 Date of work 6/87

There's no green trees within 200'-those to the North are fire killed & South is a clearcut.

5/8"x30" Iron rod N45W-8.92'
5/8"x30" Iron rod N45E-5.33'

Drove R/R spike in center of reference stumps SE & SW.

Set guard post West with decals 54-2 & survey marker.

Nailed 54-9 & BT sign to BT and reference stumps and painted band & blazes red.

Washington Plane Coordinates: Zone, Y
Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 9/22/87

Signature Larry D. Bishop Certificate No. 16337

AUDITOR'S CERTIFICATE

Filed for record this day of 19 at M. In Book of at page at the request of



Registered
Indexed, Dir
Indirect
Filed
Mailed

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 6 (2), Chapter 50, Laws of 1973.