LAND CORNER RECORD

regated Surveys: ne: Section DLC, HES, Tract, Mining Claim, India Tistory of Corner Establishment and Subsequer This corner was originally set by Deputy I Contract No. 600. Set Maple post 7" Dogwood N76½E-68 lks. 30" Fir N55½W-11 lks. Description of Evidence Found: DNR concrete monument with 3" Brass cap s Orig. 30" now 50" D-Fir snag N55½W-7.3' b rotted blaze. Orig. NE BT gone. Now 45" D-Fir stump S22E-43.3' with DNR t Now 26" D-Fir stump S75W-24.4' with DNR t	tamped: urned ag. ag.	
Tistory of Corner Establishment and Subsequer This corner was originally set by Deputy I Contract No. 600. Set Maple post 7" Dogwood N76½E-68 lks. 30" Fir N55½W-11 lks. Descri; ion of Evidence Found: DNR concrete monument with 3" Brass cap sorig. 30" now 50" D-Fir snag N55½W-7.3' brotted blaze. Orig. NE BT gone. Now 45" D-Fir stump S22E-43.3' with DNR t	tamped: urned ag. ag. ag.	
Tistory of Corner Establishment and Subsequer This corner was originally set by Deputy I Contract No. 600. Set Maple post 7" Dogwood N76/E-68 lks. 30" Fir N55/W-11 lks. Description of Evidence Found: DNR concrete monument with 3" Brass cap sorig. 30" now 50" D-Fir snag N55/W-7.3' brotted blaze. Orig. NE BT gone. Now 45" D-Fir stump S22E-43.3' with DNR to	tamped: urned ag. ag. ag.	
This corner was originally set by Deputy I Contract No. 600. Set Maple post 7" Dogwood N76%E-68 lks. 30" Fir N55%W-11 lks. Descri; ion of Evidence Found: DNR concrete monument with 3" Brass cap s Orig. 30" now 50" D-Fir snag N55%W-7.3' b rotted blaze. Orig. NE BT gone. Now 45" D-Fir stump S22E-43.3' with DNR t	tamped: urned ag. ag.	
DNR concrete monument with 3" Brass cap s Orig. 30" now 50" D-Fir snag N55%W-7.3' b rotted blaze. Orig. NE BT gone. Now 45" D-Fir stump S22E-43.3' with DNR t	urned <u>\$32 \$33</u> 1969 JCL ag.	
DNR concrete monument with 3" Brass cap s Orig. 30" now 50" D-Fir snag N55½W-7.3' b rotted blaze. Orig. NE BT gone. Now 45" D-Fir stump S22E-43.3' with DNR t	urned <u>\$32 \$33</u> 1969 JCL ag.	
가지 않는데 보고 하는 "이 경기를 제고했다. 대표 이 전 기계를 보고 하는 것이다.		
Describe Monument, Accessories and Corollary		
gram corner and indicate meridian and reference process		
There's no green trees within 2001 those is a clearcut.	to the North are fire killed & Sout	th
5/8"x30" Iron rod N45W-8.92' 5/8"x30" Iron rod N45E-5.33'		
Drove R/R spike in center of reference st	umps SE & SW.	
Washington Plane Coordinates: Zon Order Accuracy. Derived From:	Nov 24 3 50 P	CANANIA CO. WA
Pin Pointed on Photo No Date	Located at \$ \$	233
SURVEYOR'S CERTIFICATE	SAI.	
This corner record correctly represents work per under my direction in compliance with the prospective of 1973. Date 9/22/67	erformed by me or visions of Chapter	
AUDITOR'S CE	RTIFICATE	
Filed for record this day of	19at	.M. Ir
Book Jf	가는 가게 가는 하게 하는 것이 되는 것이 되는 것이 되는 것이 하는 것이 없다.	**********
Form prescribed by Bureau of Surveys and Map	Regis County Auditor Inde	sterad ked, Dir ect