

HAMPSTUR CORPORATION

					1010	Douglas A3
ΔN	ID C	ORNE	DE(CODD	LONGVIEW, V	VASHINGTON 98
¬\ ∠ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	ID C	OWITI		JUND		

Name: S-SE 1	/64 corner of S	ection 5	Corner No.:	
		aim, Indian Allotment, Federal Re		
I. History of Corner Establishm In 1977, Hagedorn, Inc. 1985, Hagedorn remonumer and added one additional BOGK 2, PAGE 236 in the found and maintained the project for PLUM CREEK I	set a 5/8" reb nted the corner l reference; (s County of Skam e corner as des	er for this corner ar with a USFS aluminum ee surveys recorded i ania). Then on July criped below. While w	n monument, as desc n BOOK 1, PAGE 142 18, 1988, HAMPSTUR Working on a corper	cribed belo 2 and in 3 CORP.
. Description of Evidence Foun	ndi			
-Found the USFS aluminum	n monument set .	in 1985 by Hagedorn,	as mentioned above	and shown
in the diagram be -Found 4 references as e shown in the diag	stablished by H	Hagedorn in 1977 and	1985, as mentioned	above and
. Describe Monument, Accessory corner and indicate meridian PS-056 Page No. 1	and reference to	map of record. Surveyor's	orner Location. Diagra Field Book No.	am <i>(986 FF</i>
LOCATION:	Date of work		WE FORT W	15"HEMLOCK W/VIS. SCRIBE
-at the head of a draw,	which	1706 EP 27" FIE, W/VIS.	200. 7.16 1 40	[1/44 55" BT] 54-3 TAG
bears North.		SCAME [1/44.5587] 543 744.	10 .4/0	
<pre>-approx. 50 ft. North of steep descent.</pre>	а	a	· · · · · · · · · · · · · · · · · · ·	
-at the existing NW corn	er of	12 - 12 - 12 - 12 - 12 - 12 - 12 - 12 -		
THE THEORETIS IN COLIN	01 01		_	
reprod, (timber lies No.	rth L	Fig Mag. W	7 C.S.SE \ FP. 21	ZUSFS ALU
reprod, (timber lies No and West).		(EP) NOS'W	PIPE	WITH STATE
reprod, (timber lies No. and West). -found blazed lines lead.		1977 RP 10.51 (Cre) ED, 90" FIR (NOW 42")	1/4 PIPE ALUM 1985 W 138	CAP, AS SE
reprod, (timber lies No and West).		(88) 10.89 W 1977 RP 10.81 (CTR) 1977 RP (NOW 42") W/ 100. TA6 - 400EP PC-10C. TA6	1/4 PIPE	CAP, AS SE
reprod, (timber lies No. and West). -found blazed lines lead.	ing	W/Jan Paka	1/4 PIPE ALUM 1985 W 138	CAP, AS SE
reprod, (timber lies No. and West). -found blazed lines lead.	ing	1977 RP 10.51 TCTR) 1977 RP 10.51 TCTR) FD. 90" FIR (NOW 42") W/ 10C. 746 - ADDED PC-/OC.746	1/4 PIPE ALUM 1985 W 138	CAP, AS SE
reprod, (timber lies No. and West). -found blazed lines lead.	ing	(18) (N69°W) 1977 RP (10.51° (CFR) FD. 90°F IR (NOW 42°) W/ 200. 746 - ADDED PC-/OC.746	1/4 PIPE ALUM 1985 W 138	CAP, AS SE
reprod, (timber lies No. and West). -found blazed lines lead.	ing	1977 RP 10.51 (CFR) 1977 RP (NOW 42") FD. 90" FIR (NOW 42") W/10C. 746 - ADDED PC-/OC.746	1/4 PIPE ALUM 1985 W 138	CAP, AS SE
reprod, (timber lies No. and West). -found blazed lines lead. South and East.	ing <i>pect-12°6</i>	W/ LOC. TAG - ADDED PC-JOC.TAG	1705 Azem 1705 W 198	127 RP FO. 16 FT. NIGHT LOC. 746
reprod, (timber lies No. and West). -found blazed lines lead. South and East. ashington Plane Coordinates:	ing pect-22° 6	W/200. 746 - ADDED PC-Joc. 746 Zone, Y	1965 1965 1967 1981 1981 1981 1981 1981 1981 1981 198	WITN STAN CAP, AS SA S BY MAGED 1977 RP FO. 16"FIR A FT. MIGH LOC. TAG
reprod, (timber lies No. and West). -found blazed lines lead. South and East. ashington Plane Coordinates:Order Accuracy	ing peci-22°6 7. Derived From:	Zone, Y	198 42 mm 198	1277 RP FO. 16" FIR LOC. 746
reprod, (timber lies No. and West). -found blazed lines lead. South and East. ashington Plane Coordinates:Order Accuracy	ing peci-22°6 7. Derived From:	Zone, Y	198 42 mm 198	1277 RP FO. 16" FIR LOC. 746
reprod, (timber lies No. and West). -found blazed lines lead. South and East. /ashington Plane Coordinates:Order Accuracy in Pointed on Photo No	ing pect-see Derived From: Date	Zone, YLocated at	198 42 mm 198	1277 RP FO. 16" FIR GFT. NEW LOC. 746
reprod, (timber lies No. and West). -found blazed lines lead. South and East. /ashington Plane Coordinates:Order Accuracy in Pointed on Photo NoSURVEYO	ing peci-32'6 Derived From: Date DR'S CERTIFICAT	Zone, YLocated at	198 42 mm 198	1277 RP FO. 16" FIR GFT. NEW LOC. 746
reprod, (timber lies No. and West). -found blazed lines lead. South and East. /ashington Plane Coordinates:Order Accuracy. In Pointed on Photo No SURVEYO This corner record correctly records.	pecu-32°6 Derived From:	Zone, YLocated at	198 42 mm 198	1277 RP FO. 16" FIR LOC. 746
reprod, (timber lies No. and West). -found blazed lines lead. South and East. /ashington Plane Coordinates:Order Accuracy in Pointed on Photo No SURVEYO This corner record correctly runder my direction in compli	pecu-save Derived From: Date PR'S CERTIFICAT represents work per ance with the pro-	Zone, YLocated at	198 42 mm 198	1277 RP FO. 16" FIR GFT. NEW LOC. 746
reprod, (timber lies No. and West). -found blazed lines lead. South and East. /ashington Plane Coordinates:Order Accuracy in Pointed on Photo No SURVEYO This corner record correctly runder my direction in complisto, Laws of 1973. Date	Date Perived From: Date Peresents work peresents which peresents work peresents work peresents with peresents which peresents which peresents work peresents work peresents which peresents work peresents work peresents work peresents which peresents work peresents work peresents which peresents with peresents with peresents with peresents with peresents which peresents with peresents with peresents which peresents with p	Located at	198 42 mm 198	
reprod, (timber lies No. and West). -found blazed lines lead. South and East. /ashington Plane Coordinates:Order Accuracy in Pointed on Photo No SURVEYO This corner record correctly runder my direction in complisto, Laws of 1973. Date	Date Perived From: Date Peresents work peresents which peresents work peresents work peresents with peresents which peresents which peresents work peresents work peresents which peresents work peresents work peresents work peresents which peresents work peresents work peresents which peresents with peresents with peresents with peresents with peresents which peresents with peresents with peresents which peresents with p	Zone, YLocated at	X Seally Washing The Child Was	1277 RP FO. 16" FIR GFT. NEW LOC. 746
reprod, (timber lies No. and West). -found blazed lines lead. South and East. /ashington Plane Coordinates: Order Accuracy in Pointed on Photo No. SURVEYO This corner record correctly runder my direction in compli 50, Laws of 1973. Date	Date Perived From: Date Peresents work peresents which peresents work peresents work peresents with peresents which peresents which peresents work peresents work peresents which peresents work peresents work peresents work peresents which peresents work peresents work peresents which peresents with peresents with peresents with peresents with peresents which peresents with peresents with peresents which peresents with p	Located at	X Seally Washing The Child Was	1277 RP FO. 16" FIR GFT. NEW LOC. 746
reprod, (timber lies No. and West). -found blazed lines lead. South and East. /ashington Plane Coordinates:Order Accuracy in Pointed on Photo No SURVEYO This corner record correctly runder my direction in complisto, Laws of 1973. Date	Derived From: Date PR'S CERTIFICAT represents work per ance with the pro-	Zone, Y. Located at Erformed by me or ovisions of Chapter 1988 LS. #18,087 Certificate No	198 42 mm 198	1277 RP FO. 16" FIR GFT. NEW LOC. 746
reprod, (timber lies No. and West). -found blazed lines lead. South and East. /ashington Plane Coordinates: Order Accuracy in Pointed on Photo No. SURVEYO This corner record correctly runder my direction in compliance of the complete of the control of the complete of the control of the complete of the control of the	pect-32's v. Derived From: Date PR'S CERTIFICAT represents work per ance with the pro October 17. AUDITOR'S	Zone, YLocated at	X PEGISTERS TO STONAL LAND	CAP, AS SE S GY MAGED 1277 RP FO. 10"FIR 40C. YAG
reprod, (timber lies No. and West). -found blazed lines lead. South and East. Yashington Plane Coordinates: Order Accuracy in Pointed on Photo No. SURVEYO This corner record correctly runder my direction in complisto, Laws of 1973. Date Senajure of Calvin J. Hampto	pect-32° 6 v. Derived From: Date PR'S CERTIFICAT represents work per ance with the pro- October 17, On AUDITOR'S	LS. #18,087 Certificate No	X YSTY REGISTERES	1277 RP FO. 16" FIR G. 16" FIR G. FT. NEW LOC. 746
reprod, (timber lies No. and West). -found blazed lines lead. South and East. Vashington Plane Coordinates: Order Accuracy In Pointed on Photo No. SURVEYO This corner record correctly runder my direction in compliance of the compliance of th	pect-32° 6 v. Derived From: Date PR'S CERTIFICAT represents work per ance with the pro- October 17, On AUDITOR'S	Zone, YLocated at	X YSTY REGISTERES	1277 RP FO. 16" FIR G. 16" FIR G. FT. NEW LOC. 746
reprod, (timber lies No. and West). -found blazed lines lead. South and East. ashington Plane Coordinates: Order Accuracy n Pointed on Photo No. SURVEYO This corner record correctly resulting in complication in complication. Laws of 1973. Date Calvin J. Hampton Calvin J. Hamp	pect-32° 6 v. Derived From: Date PR'S CERTIFICAT represents work per ance with the pro- October 17, On AUDITOR'S	LS. #18,087 Certificate No	X YSTY REGISTERES	1277 RP FO. 16" FIR G. 16" FIR G. FT. NEW LOC. 746