FILED FOR RECORD SKAMANIA CO, WASH BY Robert Glasser

EB 4 27 Pil '94 GARY M. OLSON

LAND CORNER RECORD

(THIS FORM PRESCRIBED BY THE FUBLIC LAND SURVEY OFFICE, DEPARTMENT OF NATURAL RESOURCES, PURSUANT TO RCW 58.09 ALPHA-NUMERIC INDEX DIAGRAM ON THE BACK.)

Corner Indexing information:

RGE ___Corner Code____ (Willamette Meridian)

ADDITIONAL IDENTIFIER: (e.g., BLM designation for the corner, street intersection, plat name, block, lot, etc.)

East quarter corner of Section 5, Township 1 North, Range 5 East, Willamette Meridian.

118647

BOOK /4 PAGE 232

Skamania County Washington:

AUDITOR'S USE

Land Surveyor Information: (or Public Officer as per RCW \$8.09.090)

This corner record correctly represents work performed by me or under by direction in conformance with the Survey Recording Act.

Company or agency: Minister & Glaeser Surveying, Inc. 2208 E. Evergreen Blvd. Vancouver, WA. 98661 Phone: (206) 694-3313 Fax: (206) 694-8410.

W. GC SALLAND 5-30

Washington Plane Coordinates: Order:

Zone:

E:

Datum (Date of adjustment):

Corner Information: Use the space below to provide the following information regarding the corner.

(1) Pertinent Corner History: The original survey was conducted by Deputy Surveyors, Lewis Van Vleet and John Newsom, under Contract No. 47, dated the 23rd day of April, 1859. The survey was conducted between April 26th and April 29th, 1859. Set a quarter section post common to Sections 4 and 5. R.P.'s were as follows:

30" diameter Fir, South 81° West, 51 Links. 4" diameter Vine Maple, South 81° East, 24 Links.

Skamania County Engineers records, shows said East quarter of Section 5, was monumented with a 5/8" Iron Rod set by County Engineer. referenced with a Iron Fence post with Tag X, 1 foot South of Iron Rod.

In August of 1973, W.F. Hagedorn conducted a survey (Book 1, page 6, of Skamania County records), and found an Iron Rod 2642.15 North of the Southeast corner of Section 5 and 2650.92 South of the Northeast corner of Section 5. Held as the East quarter corner of Section 5.

> Registered ad sed. Dir Sal-met Francis Mailed

In January of 1974, Olson Engineering conducted a survey (Book 1, page 10, of Skamania County records), and found a 5/8" Iron Rod 2614.15 North 1°11'34" East, of the Southeast corner of Section 5, and 2650.92 South 1°11'42" V of the Northeast corner of Section 5. Held as the East quarter corner of Section 5.


(2) Evidence Found at the Corney: No original evidence found. The position of this corner was calculated based on Surveys found in records of Skamania County, Surveys Book 1, page 6 and page 10. 5/8" Iron Rod was accepted as the corner based on reputation and use.

(3) Corner Perpetuation Information:

Refer to the following records of surveys:

Surveys

Book 1, page 6 Book 1, page 10



Information on this form; on accurate description and location, in reference to the opener position, of all monuments and accessories (a) found at the corner and (b) placed of placed at the corner and (c) basis of bearings used to describe or locate such consuments or accessories; and (d) corollary information that may be helpful to relocate or identity the corner position.

EPACE FOR ADDITIONAL COMMENTS