121805 BOOK 148 PAGE 646 LAND CORNER RECORD

(THIS FORM PRESCRIBED BY THE PUBLIC LAW SURVEY OFFICE, DEPARTMENT OF HATURAL RESOURCES, PURSUANT TO RCV 58.08. ALPHA-NUMERIC THOFY DIAGRAM ON THE BACK.)

\_\_\_ CORNER CODE

FILED FUR RECORD SKAMANIA GO. WASH BY Perry Transow

Mar 13 12 p. PN '95 AUDITOR &

(See instructions on back of LCR) ADDITIONAL IDENTIFIER: (e.g., BLM designation for the corper, street intersection, plat name, block, lot, etc.)

‡ corner of Sec. 31, T2N,R6E and Sec. 6, T1N,R6E

GARY M. OLSON

AUDITOR'S USE

LAND SURVEYOR INFORMATION: (or Public Officer as per RCW 58.69.090)

This corner record correctly represents work performed by  $\infty e$  or under my direction in conformance with the Survey Recording Act.

COMPANY OR AGENCY: TRANTON SURVEYING, INC.

RIE 6 E

CORNER INDEXING INFORMATION:

(Willamette Heridian)

ADDRESS:

TUP 2 N

PO BOX 287 - 412 W. JEFFERSON

BINGEN, WA 98605-0287

509 / 493-3111



WASHINGTON PLANE COORDINATES:

E:

ADNE:

DATUM (Date of adjustment):

CORNER INFORMATION: Use the space below to provide the following information regarding the corner:

(1) Pertinent Sorner History. (2) Evidence Found at the Corner, and (3) Corner Percetuation Information. Please title and number the parts of your discussion accordingly. If additional space is needed use the back. (For (3), diagram the references. Also, provide the cross-reference to a map of record, if applicable, the surveyor's field book no./page vo., and the date of work.) (See the back of this form for the requirements of the Survey Recording Act.)

GLO in 1859 set a post for this corner, from which bear:
8" alder, S61W, 61 links; 4" willow, S89E, 18 links
GIO in an 1883 retracement found no remains of \$\frac{1}{2}\$ corner and set a post
the corner, from which bear: 40" fir, NO4\frac{1}{2}E, 60 links;

8" dogwood, \$84E, 96 links


6 ) in a 1917 retracement found a post, greatly decayed, and replaced it with a 1" iron post, 3 ft. long, with brars cap, 26" deep, from which bear: Original fir, N76E, 33 ft.(50 lks); Oreginal fir, S08E, 44.22 ft. (67 1ks)

A 1961 survey by Marx Bros. of Gresham, Oregon found the GLO monument. Survey is dated 4/5/61, on file in the Skamania Co. Engineer vault. DNR in 1969 found both BT's and set a concrete monument with brass cap by distance intersections. No GLO IP/BC was noted, and from their monument bear: 36" fir, N78E, 33 ft.: 14" alder, West, 18 ft.

2. Found DNR monument and remains of rusted Skamania Co. location post.

3. Also found GLO IP/BC 4" bolow the ground, marked as shown, from which bear: 48" rotted D-fir stump, N78E, 32.29 ft. to face with visible scribing 30" rotted D-fir stump, S08E, 44.58 ft. to face with visible scribing 24" D-fir, S66W, 44.73 ft. to face on root collar scribed WT DNR monument, N76W, 1.79 ft. DNR witness tree not found.

Corner lies approximately 40 feet South of an old east-west logging road. I held the GLO IP/BC as the correct location for the present survey. This document supercedes one inadvertently filed in Volume 316 at Page 639 of Land Corner Records, Klickitat Co. Auditor on 11/22/54. A 1961 survey by Marx Bros. of Gresham, Oregon found the GLO monument.



RCW 58.09.060 (2) requires the following information on this firm: an accurate description and location, in reference to the corner position, of all monuments and accessories (a) found at the corner and (b) placed or replaced at the corner; (c) basis of bearings used to describe or locate such monuments or accessories; and (d) corollary information that may be helpful to relocate or identify the corner position.

SPACE FOR ADDITIONAL COMMENT:

KOPQRSTUVWXY