

127151

BOOK 162 PAGE 21

FILED FOR RECORD
SKAMIA CO. WASH
BY Jerry Olson


JAN 21 12 35 PM '97

G. Lowry
AUDITOR
GARY M. OLSON

LAND CORNER RECORD

GRANTOR: JERRY C. OLSON This corner record correctly represents work performed by me or under my direction in conformance with the Surveying Act.

COMPANY OR AGENCY: Olson Engineering Inc.

ADDRESS: 1111 Broadway
Vancouver, Wa 98660**OLSON**
ENGINEERING INC.1111 Broadway, Vancouver WA 98660
(206) 450-1203 • (206) 508-9126 • Fax (206) 910-1117

GRANTEE: PUBLIC

LEGAL: NE 5 TWP: 1N

RGE: 5E

CORNER CODE: A-9

ADDITIONAL IDENTIFIER: (BLM designation, street or plat names, block, lot, etc.)

NORTHEAST CORNER OF SECTION 5

COUNTY: SKAMIA

WASHINGTON PLANE COORDINATES: N:

E:

ORDER:

ZONE:

DATUM (Date of adjustment):

CORNER INFORMATION: Discuss the history, evidence found, and perpetuation of the corner. Diagram the references; provide the date of work; and, if applicable, a reference to a map of record and/or the field book/page no. Use the back, if needed.

The original Northeast Section corner was established by L. Van Vleet and John Newsom under contract #47 in 1859 as a post with accessories of: A 40" fir South 36° East 96 links, an 18" Fir North 82° East 126 links an 8" Willow South 36° West 119 links and a 7" Willow North 75° West 37 links.

In 1911 C. La Barre visited the site and reset the post from 2 of the bearing trees "one a stump the other green and a stump of third." (Book 5, Page 4)

A survey by Fred Laws (date unknown) shows that during a dependent resurvey the topographic calls matched the general land office notes and at the Northeast corner he established new accessories of: A 30" Fir North 44° West 472 links, a 40" Fir North 55° East 227 links a 40" Fir South 15° East 39 links and a 30" Fir South 54° West 147 links.

In 1980 Olson Engineering crews found a Washington Department of Game Concrete Monument Set. West 2641.13 feet from the North quarter corner of Section 4 and South 2570.11 feet from the East quarter corner of Section 32, Township 2 North, East 5 East. Olson records do not indicate the existence of any original or secondary accessories.

REFERENCES:

Hagadorn Book 1, Page 6

(40380001.1or)

This form is in compliance with the intent of RCW 65.04.045 and prescribed by the Public Land Survey Office, Department of Natural Resources - 1/97.

Registered ☒
Indexed, Dir ☒
Indirect ☒
Filmed ☒
Mailed ☒

MARK THE CORNER LOCATION ON THE DIAGRAM BELOW AND FILL IN THE CORNER CODE BLANK ON THE OTHER SIDE.


(1) For corners located at the intersection of two lines (Section corners, quarter corners and sixteenth corners):

(a) The corner code is the alpha-numeric coordinate from the diagram below that corresponds to the appropriate intersection of lines.

(2) For corners that are not located at the intersection of two lines (Meander corners, DLC's, HES's, reservation boundaries, mining claims, etc.):

(a) For corners that are on one line only the corner code is the line designation and the related line segment; i.e., a corner on line 5 between "B" and "C" is designated BC-5.

(b) For corners that are between lines the corner code is both line segments; i.e., a corner in the SE1/4 of the SE1/4 of section 18 is designated MN-4-5.



RCW 58.09.060 (2) requires the following information on this form: an accurate description and location, in reference to the corner position, of all monuments and accessories (a) found at the corner and (b) placed or replaced at the corner; (c) basis of bearings used to describe or locate such monuments or accessories; and (d) ancillary information that may be helpful to relocate or identify the corner position.

SPACE FOR ADDITIONAL COMMENT: