

- 6 -

- 1 5 H.P. 190 R.P.M. 440 volt gear motor.
- 1 5 H.P. 123-163-273-507 R.P.M. 440 volt Lima 4 speed gearshift drive motor.
- 1 5 H.P. 1800 R.P.M. 440 volt motor.
- 1 7½ H.P. 1800 R.P.M. 440 volt motor.
- 1 25 H.P. 1800 R.P.M. 440 volt motor.

Conveyors

- 1 Barker Conveyor - From under Barker 40' long, #112 chain.
- 1 Motor - 3 H.P. 30 R.P.M. 220/440 volt U. S. Synchro gear motor.
- 1 Conveyor - From Barker Conveyor to Hog, 90' long, #112 chain.
- 1 Motor - 5 H.P. 20 R.P.M. 220/440 volt U. S. Synchro gear motor.
- 1 Lathe Core Conveyor with motor - From Lathe to Core Dock 50' long, #112 chain.
- 1 Motor - 3 H.P. 45 R.P.M. 220/440 volt Pacific motorized speed reducer.
- 1 Belt Conveyor - 120' long, 24" belt conveyor from Equalizer Saw and Skinner Saw.
- 1 Motor - 5 H.P. 20 R.P.M. 220/440 volt Gearhead motor.
- 1 Belt Conveyor - 100' long, 30" belt conveyor from previous conveyor under Tipple on way to Hog.
- 1 Motor - 7½ H.P. 20 R.P.M. 220/440 volt U. S. Synchro gear motor.
- 1 Hog Feed Conveyor - 10 chains 12' long in 36" wide steel trough.
- 1 Conveyor - From Hog on way to Boiler House - 48' long, 2 - #112 Chain.
- 1 Motor - 7½ H.P. 20 R.P.M. 220/440 volt U. S. Synchro gear motor.
- 1 Boiler House Conveyor - 72' long link chain conveyor to Boiler House.
- 1 Motor - 7½ H.P. 20 R.P.M. 220/440 volt U. S. Synchro gear motor.
- 1 Fish Tail Conveyor - From under Fish tail saw on way to Chipper, 24' long, 24" belt.
- 1 Motor - 5 H.P. 190 R.P.M. 220/440 volt U. S. Synchro gear motor.
- 1 Chipper Feed Conveyor - 6' long, 6 chain steel conveyor to Chipper.
- 1 Chipper Conveyor - 40' long chain conveyor from under Chipper on way to railroad cars.
- 1 Motor - 5 H.P. 20 R.P.M. 220/440 volt U. S. Synchro gear motor.
- 1 Railroad Car Conveyor - 130' long, belt conveyor to railroad car.
- 1 Motor - 7½ H.P. 20 R.P.M. 220/440 volt U. S. Synchro gear motor.

Dust Collector System

- 1 Exhauster - #80 single steel plate Exhauster arranged for direct motor drive, with motor base.
- 1 Motor - 100 H.P. 704 R.P.M. 220/440 volt Fairbanks Morse motor base and flexible coupling. Serial #590218.
- 1 Piping - To Sander, Branch to 2 Belt Sanders, Branch to Equalizer, to Skinner Saw, Discharge to Boiler House, To Shim Cutter, To Stripper, to Shim Hood.
- 1 Exhauster (in Northwest Addition) - 50" Single steel plate Exhauster arranged for direct drive with motor base.
- 1 Motor - 25 H.P. 1170 R.P.M. 220/440 volt General Electric ball bearing motor. Serial #XD6735542.
- 1 Piping - Suction - From Surfacar, to Mattson Rip Saw, to Jointer, to Core Saw, Discharge to Cyclone, Drop to #1 Exhauster.
- 1 Exhauster - #45 Single steel plate Exhauster, arranged for direct motor drive.