

93220

LAND CORNER RECORD

T 7N. R 5E W.M.
Segregated Surveys:County
Corner Code No. J-23Name: SOUTH QUARTER CORNER SECTION 12 Corner No.:
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve Township

1. History of Corner Establishment and Subsequent Restoration:
GOVERNMENT LAND OFFICE SURVEY 1900

2. Description of Evidence Found:

FND: 2" x 5' PIPE

WEY. CO. RP'S

6" SILVER FIR STUMP N 78° W 0.40' WEY. TAG

28" HEMLOCK STUMP S 28° E 31.00' WEY. TAG & NAIL

ASSUMED OBT'S DESTROYED BY CAT WORK IN AREA

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 161. Page No. 2 Date of work 9-18-81

ALL BT'S HAVE:

6" RED BAND AROUND THEM

54-3 & 54-4 SIGNS

DISTANCES TAKEN HORZ. TO SURVEY TAG
NAILED IN TOP OF NEWLY SCRIBED B'S.

REF. POINT 1/2" x 30" REBAR

PLASTIC CAP LS 15652

S 28° E, 2.23' TO STUMP

SET 2 1/2" x 30" PIPE 26" IN GROUND
IN MOUND OF STONE MARKED:

T 7N R 5E

1/4 S 12

S 13

1981

LS 15652

BT

4" HEMLOCK

SCRIBED X BT

WEY. CO. RP

28" HEMLOCK

WEY. CO. TAG & NAIL

54-3 SIGN ON STUMP

GIVING DIST. TO REBAR

FROM STUMP AND

REBAR TOP CORNER

Washington Plane Coordinates:

Zone, Y

Order Accuracy. Derived From:

Pin Pointed on Photo No.

Date

Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or
under my direction in compliance with the provisions of Chapter
50, Laws of 1973. Date Oct 10, 1981

Signature

Certificate No.

93220

AUDITOR'S CERTIFICATE

Filed for record this 22nd day of October 1981 at 11:00 A. M. In
Book 7/5 of Monuments at page 8 at the request of

Isabel Messenger by B. Balcock
County Auditor