

LAND CORNER RECORD

T. 4 N. R. 7E, W.M.
Segregated Surveys:
Name: Section Corner
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

County
Corner Code No. 8-17



1. History of Corner Establishment and Subsequent Restoration.

Corner established in July or Aug. 1897 by Deputy Jacob Richardson under his contract No. 457.

Marked orig. 4" Maple post.
36" Fir N41E, 30 lks..
36" Fir S20E, 77 lks..
30" Fir S56W, 179 lks..
36" Fir N67W, 54 lks..

2. Description of Evidence Found:

U.S.F.S. 2" Brass cap on 2" Iron pipe 1" above ground. 3/4" Iron pipe S45E, 3 ft. accepted FS Brass cap.
Orig. 36" now 48" rotted D-Fir stump no marks remaining, 117.4, 42.2 ft. to face.
Orig. 36" now 40" rotted D-Fir stump N41E, 58.7 ft. to face, no marks remaining.
Orig. 36" now 48" rotted D-Fir stump S20E, 54.0 ft. to face, scribing NF visible.
Bearing Tree in Sec. 27 possible windfall-does not fit for bearing.
Remark by Olsen 9" D-Fir N17E, 5.11 ft to 1/8 spike in bottom of 4 blazes.
Fence South and West.
See Wind River Experimental Forest Timber Survey Report-1933 corner listed as set from original evidence.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 3. Page No. 3. Date of work Oct. 1981.

Set guard post West with sign 54-3 and BM 102 6600.
Nailed 54-4 and BT signs to all 4" and painted hard red blazes red.
New Bearing Trees:

2" D-Fir N41E, 30.0 ft. scribed 1/8" 1/2" upper blaze and a lower blaze scribed 1/8" and with a 3/4" brass disk stamped 113 1 1/2.
36" D-Fir S20E, 77.0 ft. scribed 1/8" 1/2" upper blaze and a lower blaze scribed 1/8" and with a 3/4" brass disk stamped 113 1 1/2.
1" D-Fir N72E, 54.0 ft. scribed 1/8" 1/2" upper blaze and a lower blaze scribed 1/8" and with a 3/4" brass disk stamped 113 1 1/2.
1" D-Fir N40E, 58.0 ft. scribed 1/8" 1/2" upper blaze and a lower blaze scribed 1/8" and with a 3/4" brass disk stamped 113 1 1/2.

Washington Plane Coordinates: Zone, Y, X
Order Accuracy. Derived From:
Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 11/15/81

Signature Larry D. Bishop Certificate No. 16357

[SEAL]



AUDITOR'S CERTIFICATE

Filed for record this 18th day of December 1981 at 9:10 A.M. In Book 4/7 of Monuments at page 8 at the request of

Larry D. Bishop
J. M. Olson
County Auditor