

LAND CORNER RECORD

T. N. R. W.M. Shamania County
Segregated Surveys: Corner Code No. 9-17
Name: One-Eighth corner Corner No.:
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

N/A

2. Description of Evidence Found:

N/A

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 3 Page No. 15 Date of work Oct. 1981

Set 2 "x24" gal. steel pipe with a 2" diameter hole in the surface

1 foot South of the edge of pavement of Highway 102. Set:

Set square bolts East and North 122.40 feet from the corner of the road with sign 14-5 and 102 Steel.

Coiled 1/4" and 1/2" pipes to 15' and painted lead and blazed red.

New bearing trees:

12" D-11r 34.1, 34.3 ft. scried 11/4 12" D-11r 34.1 and a lower blaze scried 11 and with a 1/2" disk stamped 11/4 1332.

22" D-11r 34.1, 34.2 ft. scried 11/4 22" D-11r 34.1 and a lower blaze scried 11 and with a 1/2" disk stamped 11/4 1332.

Washington Plane Coordinates: Zone, Y, X
Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 11/15/81


Signature *Larry S. Bishop* Certificate No. 16337

AUDITOR'S CERTIFICATE

Filed for record this 18th day of December 1981 at 9:10 A.M. In Book 4/7 of Monuments at page 9 at the request of

Bishop Surveying Inc.
J. M. Olson
County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.



ROLL 121981.D
MARRIAGE APPLICATIONS
DAILY RECORDINGS
BOARD OF COUNTY COMMISSIONERS