

LAND CORNER RECORD

Skamania

County

T. 7 N. R. 6E, W.M.

Corner Code No. J-9

Segregated Surveys:

Name: Section corner

Corner No.:

DLC. HES. Tract, Mining Claim, Indian Allotment Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

This corner was originally set by Deputy Lewis D.W. Shelton in July 1899, & Oct.-Dec. 1900 under Contract No. 552.

Remonumented by Floyd A. Brooks, Cadastral Surveyor in Oct. & Nov. 1961.

Set Wh. Fir post.

Set Iron post with Brass cap.

Scribed 26" Wh. Fir N65 $\frac{1}{2}$ E-67 lks..

Scribed 13" Hemlock N58E-49 lks..

36" Wh. Fir S70E-12 lks..

20" Hemlock S55E-21 $\frac{1}{2}$ lks..

30" Wh. Fir S43 $\frac{1}{2}$ W-13 $\frac{1}{2}$ lks..

12" Wh. Fir S40 $\frac{1}{2}$ W-29 lks..

10" Wh. Fir N58 $\frac{1}{2}$ W-41 lks..

2. Description of Evidence Found:

Corner destroyed by fire trail construction.

Orig. 10" Wh. Fir now 28" Hemlock snag 12 ft. tall-healed blaze, N38 $\frac{1}{2}$ W-41 lks..

Orig. 36" now 20" Wh. Fir rotted stump S70E-12 lks.-no marks remaining.

Brooks 20" now 22" Hemlock S55E-21 $\frac{1}{2}$ lks. scribing visible on partially healed blaze.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 2 Page No. 11 Date of work June 1962

Set 2 $\frac{1}{2}$ "x30" Aluminum pipe with a 2 $\frac{1}{2}$ " Aluminum cap. Marked:

New Bearing Trees:

8" D-Fir N64W, 40.6 ft. scribed T.M.6ES1 upper blaze and a lower blaze scribed BT and with a 3/4" Brass disk stamped PLS 1633.

4" D-Fir N61E, 8.2 ft. scribed BT only on lower blaze and with a 3/4" Brass disk stamped PLS 1633.

8" D-Fir S34W, 31.7 ft. scribed T.M.6ES1 upper blaze and a lower blaze scribed BT and with a 3/4" Brass disk stamped PLS 1633.

Set guard post North with sign 54-4.

Nailed 54-4 and BT signs to BT's and painted band and blazes red.

T. 7 N.	R. 6 E
S8	S9
S17	S16
1962	
PLS 16337	



Washington Plane Coordinates: Zone, Y, X

Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date

Signature *Larry D. Miller*

16337

Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this 13th day of JULY 1962 at 12:20 P.M. In Book 7/6 of MONUMENTS at page 16 at the request of

BISHOP SURVEYING INC

H. M. Olson

County Auditor