

94735

LAND CORNER RECORD

Sitamaia

T 7 N, R 6E, W.M.

County Corner Code No. G-17

Segregated Surveys:

Name: One-quarter corner

Corner No.:

DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

This corner was originally set by Deputy Lewis D.W. Shelton in July 1929, & Oct.-Dec. 1900 under Contract No. 552. Set Fir post. Scribed 6" Wh. Fir S74E-25 lks.. 36" Cedar S75E-50 lks..

Remonumented by Floyd A. Brooks, Cadastral Surveyor in Oct. & Nov. 1961. Set concrete post with Brass cap. Scribed 13" Cedar N24E-152 lks.. 10" Hemlock N56E-96 lks..

2. Description of Evidence Found:

BLM concrete post with Brass cap. Orig. 36" now 62" sawed stump S75E-50 lks.-rotted blaze. Orig. 6" now rotted 13" stump S74E-25 lks.-scribing visible on opened blaze Brooks 10" now 15" sawed Hemlock stump 8 ft. tall N56E-96 lks.-healed blaze. Brooks 13" now 20" Cedar N24E-152 lks.-healed blaze.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 2 Page No. 15 Date of work July 1982

There are no live trees or other bearing objects available in Section 10.

Set guard post South with sign 54-4 and BM 102 decal. Nailed 54-4 and BE signs to BE's and painted band and blazes red.



Washington Plane Coordinates: Zone, Y, X Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date July 30, 1982

Signature Larry D. Bishop Certificate No. 16337



AUDITOR'S CERTIFICATE

Filed for record this 14 day of Sept 1982 at 1:30 P.M. In Book 7/6 of Monuments at page 23 at the request of

Signature Larry D. Bishop County Auditor