

94736

LAND CORNER RECORD

T 7 N, R 6E, W.M.
Stamania County
Corner Code No. E-13
Segregated Surveys:
Name: Section Corner Corner No.
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

This corner was originally set by Deputy Lewis D.W. Shelton in July 1899, & Oct.-Dec. 1900 under Contract No. 552.
Set Cedar post.
Scribed 60" Fir N703/4E-48 lks..
54" Fir S473/4E-44 lks..
22" Cedar S87W-25 lks..
10" White pine N80W-28 lks..
Remonumented by Floyd A. Brooks, Cadastral Surveyor in Oct. & Nov. 1961.
Set Iron post with Brass cap.
Scribed 3" Hemlock S8W-18 1/2 lks..
5" Hemlock N16W-26 1/2 lks..


2. Description of Evidence Found:

BIM 2 1/2" Iron pipe with a 3" Brass cap.
Orig. 60" now 72" D-Fir healed blaze N71E-48 lks..
Orig. 54" now 72" D-Fir healed blaze S47E-44 lks..
Orig. 22" now 28" Cedar stump rotted blaze S87W-25 lks..
Brooks 3" now 6" Hemlock healed blaze S8W-18 1/2 lks..
Brooks 5" now 8" Hemlock healed blaze N16W-26 1/2 lks..

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. Page No. Date of work

Nailed signs 54-4 and 8E signs on BT's, painted red band and blazes red on BT's.
Set guard posts East and South with sign 54-4 and BM 102 decals.

Registered 6
K.



Washington Plane Coordinates: Zone, Y X
Order Accuracy. Derived From:
Pin Pinned on Photo No. Date Located at.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date July 30, 1982
Signature Larry D. Bishop Certificate No. 16337

[SEAL]



AUDITOR'S CERTIFICATE

Filed for record this 14 day of Sept 1982 at 1:30 P.M. In Book 7/6 of Monument at page 24 at the request of Larry D. Bishop
Larry M. Olson County Auditor