

94740

LAND CORNER RECORD

T 7 N, R 6E, W.M. Skamania County Corner Code No. J-13
Name: Section corner Corner No.
DLC, RES. Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

This corner was originally set by Deputy Lewis D.W. Shelton in July 1899, & Oct.-Dec. 1900 under Contract No. 552.

Remonumented by Floyd A. Brooks, Cadastral Surveyor in Oct. & Nov. 1961.

Set Cedar post.

Set concrete post with Brass cap. Scribed 9" Wh.Fir N68 1/2 E-38 1/2 lks.. 8" Wh.Fir S82 1/2 E-46 lks.. 8" Hemlock N3W-37 lks..

Scribed 30" Cedar N49 1/4 E-46 lks.. 5" Wh.Fir S65 3/4 E-34 lks.. 10" Wh.Fir S29W-29 lks.. 40" Cedar N63 1/2 W-9 lks..

2. Description of Evidence Found:

Shattered remains of BIM concrete post-the Brass cap is gone. Orig. 10" now 24" sawed Wh.Fir stump S29W-29 lks.-healed blaze. Orig. 40" now 40" Cedar sawed stump N63W-9 lks. scribing visible on partially healed blaze.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 6 Page No. 7 Date of work July 1982

Set 2 1/2"x30" Aluminum pipe with a 2 1/2" Aluminum cap. Buried remains of concrete post in hole next to monument set. Marked:

New Bearing Trees:

6" Alder N65W, 29.0 ft. bark scribed T7NR6ES9BT and with a 3/4" Brass disk stamped PLS 16337.

T.7N R.6E

6" D-Fir N48E, 44.1 ft. scribed T7NR6ES10 upper blaze and a lower blaze scribed BT and with a 3/4" Brass disk stamped PLS 16337.

S9 | S10

6" Alder S89E, 36.9 ft. bark scribed T7NR6ES15BT and with a 3/4" Brass disk stamped PLS 16337.

S16 | S15

10" Hemlock S17W, 97.0 ft. scribed T7NR6ES16 upper blaze and a lower blaze scribed BT and with a 3/4" Brass disk stamped PLS 16337.

1982

PLS 16337

Nailed 54-4 and BT signs to BT's and painted band and blazes red. Set guard posts North and East with sign 54-4 and BM 102 decal.

Washington Plane Coordinates: Zone, Y Order Accuracy. Derived From: X

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date Aug 4, 1982

Signature Larry D. Bishop Certificate No. 16337

[SEAL]



AUDITOR'S CERTIFICATE

Filed for record this 14 day of Sept. 1982 at 1:30 P.M. In Book 716 of Monumental at page 28 at the request of

Signature Larry M. Olson County Auditor