

LAND CORNER RECORD

Skamania County
T. 3 N. R. 8 East, W.M. Corner Code No. A-5
Segregated Surveys:
Name: n/a Corner No.: n/a
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite

- History of Corner Establishment and Subsequent Restoration:
Originally set by G.L.O. surveyor, Robert A. Webster, in 1896.
No restoration found.
- Description of Evidence Found:
18" Fir B.T. snag at N 82 W, 82.5 feet from corner position.
42" Fir B.T. at N 52 E, 9.73 feet from corner position.
19" Fir B.T. with visible scribe at S 69 E, 32.0 feet from corner position.
46" Fir B.T. at West 10.27 feet from corner position.
- Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 60. Page No. 57 Date of work 11-18-82

Shown on D.N.R. Final Map #462. See corner diagram on reverse side.

On 11-18-82, the D.N.R. set a standard D.N.R. iron pipe with stamped brass cap at intersection of record distances from live B.T.'s (distances measured from B.T. faces).

Washington Plane Coordinates: South Zone, Y 166,637.57 - X 1,659,531.07 -
3rd Order Accuracy. Derived From: 1975 Olson Eng. survey data at S.W.
corner Sec. 5 (Recorded in Bk. 1. page 54, Records of Skamania County)
Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date Sept. 29, 1982
M. A. Kinnaman 11977
Signature Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this 6th day of OCTOBER 1983 at 1:40 P.M. In Book 3/8 of RECORDS at page 68 at the request of Washington State Department of Natural Resources
M. Olson by d. New, Dep
County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.

GLO Survey of 1896

East on N boundary Sec 6

78.88 Set post

24" Fir	N48E	131.	8.50'
14" Fir	S72E	501	33.0"
24" Fir	West	151	9.90'
16" Fir	N84W	1251	82.50

Section Corner $\frac{31}{25}$ T3 & 4N R.0E

Found 3 live BT's & 1 rotted BT S.299.

Opened up the SE BT and found remnants of scribing on the badly burned face. Did not open the other BT's.

Set the pipe & cap by intersecting the distances from the 2 BT's faces, allowing for growth on the 2 BT's not opened up. The pattern won't work by measuring from the centers of the BT's.

No other surveys of record

corner is DNR tree sta. 125

11-18-82

LAIRD
GORDON
BRESSLER

57
600.27

