

LAND CORNER RECORD

Skamania Clark County
 T 2 N, R 4 East, W.M. Corner Code No. 2- 23
 Segregated Surveys:
 Name: n/a Corner No.: n/a
 DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

Originally set by Justin Chenoweth during 1856 G.L.O. survey of TIN R4E. Restored with 3/4" pipe and cap, date and by whom set unknown. In 1971, Dept. of Game single proportioned corner from 1 mile west and 1/2 mile east and set 1-1/4" pipe with plug. In 1977, Wallace and Assoc. used 1-1/4" pipe as shown in Book 7 pg 106.

2. Description of Evidence Found:

Above mentioned 3/4" pipe and end cap at N 83 E, 96.60 ft. from corner position. Not accepted this survey. Above mentioned Dept of Game 1-1/4" pipe with plug at S 62 W, 19.16 ft. from corner position. Not accepted this survey.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 607.07A Page No. 21 Date of work 18 Jan, '82

Set standard D.N.R. concrete monument and stamped brass cap at calculated mid-point corner position.
 Shown on D.N.R. Final Map 441.
 See sketch on back.



Washington Plane Coordinates: South Zone, Y 104,899.08 X 1,550,002.93
 3rd Order Accuracy. Derived From: USE & GS 'Ells' and DNK 3-3N-4E

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date Sept 28, 1983

Signature

M. A. Kinnaman
 11977
 Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this 6TH day of OCTOBER 1983 at 1:55 P.M. In Book 2/4 of MONUMENTS at page 1 at the request of Washington State Department of Natural Resources

M. A. Kinnaman by d. Davis, Dep.
 County Auditor

GLO at 1855

40.00 Set post --

A Fir 50" S10E 133' 87.78'

B Fir 40" N26E 178' 117.48'

S 1/4 corner Sec. 36 T2N R4E

Found Pipes as shown on sketch. Dept. of Game single proportioned this corner from one mile west and 1/2 mile east, using the wrong position for the corner 1/2 mile east. Hagedorn, Inc.'s remonumentation of $\frac{35}{21}$ (book 11, pg 8A & 8B) and the DNR's remonumentation of $\frac{34}{16}$, at their original position, make D.O.G.'s proportionment of this corner incorrect.

In 1977, Wallace & Assoc used D.O.G.'s pipe,
Book 7, Page 106

I was unable to determine the origin of the 3/4" pipe

