

96948

RES 20-1808(9-77)

STATE OF WASHINGTON
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS

BOOK 3/10 PAGE 33

LAND CORNER RECORD

T. 3 N, R. 10 East, W.M. Skamania County
Segregated Surveys: Corner Code No. N - 13 -
Name: n/a Corner No.: n/a
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

Originally set by G.L.O. Surveyors, Smith and Spray, in 1875.
A 1" iron pipe was set, date and by whom set is unknown.

(See additional corner descriptive data on reverse.)

2. Description of Evidence Found:

2 B.T's.:

22" Fir stump with axe marks at N.45 W., 15.3 ft.
30" mound of rotten wood and bark at S.62 W., 22.5 ft.
Above described 1" iron pipe set next to the corner post of fence intersection.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 603.26A Page No. 27 Date of work 9-1-'82

Shown on D.N.R. Final Map # 483.
See corner diagram on reverse side.
Replaced iron pipe with standard
D.N.R. concrete monument with
stamped brass cap.



Washington Plane Coordinates: South Zone, Y 149,781.14 X 1,732,619.21
3rd Order Accuracy. Derived From: Ties to USC & GS "Brought"

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date JAN 3, 1984

Signature

11977
Certificate No.

[SEAL]



AUDITOR'S CERTIFICATE

Filed for record this 9th day of JANUARY 1984 at 11:15 A.M. In Book 3/10 of MONUMENTS at page 33 at the request of Washington State Department of Natural Resources.

J. M. Olson Jr. A. Davis, Rep.
County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.

GLO Survey of 1875

West on a true line between 15 & 22

80.00 Set a post --

12" Maple	N70E	13L	8.58
18" Fir	N45W	19L	12.54
18" Fir	N70E	31L	20.46
6" Fir	S15E	23L	15.18

Section Corner $\frac{16}{21} \frac{15}{22}$ T3N R10E

Found 2 BT's as shown in sketch.

Found 1" iron pipe marking corner. This pipe was next to the corner post of the fence intersection, and was bent over to the east.

The DNR mon. was set plumb over the base of the pipe. Placed pipe against fence next to monument

Other surveys of record:

Terra Surveying Stamania Co BK 2 Pg 45 12/81

Lawson Land Surveying Stamania Co BK 2, pg 16 & 17 5/81

Olson Engr. Stamania Co BK 1 pg 189 5/79

9-1-82

LAIRD
GORDON
BRESSLER
MORRIS

27
603.26A

