

LAND CORNER RECORD

T 4 N, R 7 East, W.M. Skamania County
Segregated Surveys: Corner Code No. Z-23

Name: Recinds L.C.R. # 96790, dated 1 December 1983 Corner No.: n/a
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:


Originally set by G.L.O. surveyor, Jacob Richardson, during 1895 G.L.O. survey.
In 1903, this corner was found by G.L.O. surveyor, Robert F. Whitham during Retracement survey.
In 1983, the Dept. of Natural Resources set a D.N.R. concrete monument with stamped brass cap at single-proportioned corner position.

2. Description of Evidence Found:

Above described D.N.R. concrete monument with stamped brass cap.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.24 Page No. 52 Date of work 9-25-'84

Reset found D.N.R. concrete monument to newly calculated single-proportioned corner position based on reset northeast corner of Section 1 T.3 N., R.7 E., W.M. Date re-stamped on brass cap '1984'.
Corner shown on D.N.R. Final Map # 477.
See corner diagram on reverse side.



S.S.

Washington Plane Coordinates: South Zone, Y 166,151.64, X 1,645,511.36
3rd Order Accuracy. Derived From: Ties to USC & GS Control Stations
'Greenleaf' and 'Sedum Point'.

Pin Pointed on Photo No. _____ Date _____ Located at _____

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date Jan. 15, 1985

Signature M. A. Kinnaman Certificate No. 11977



AUDITOR'S CERTIFICATE

Filed for record this 21st day of JANUARY 1985 at 12:00 P.M. In Book 47 of MONUMENTS at page 94 at the request of Washington State Department of Natural Resources.

J. McLean County Auditor

GLO of 1895

West 40.00 set post
6" fir NW 30L
4" fir SSE 10L

South 1/4 corner, Section 36 T4N R7E

No GLO evidens. found

Calc. position falls in a 36" fir stub

Set RM's as shown.

Both RM's are on the section line

9-25-84

Gordon
Brassler
Hartlin 52
600.14

