

LAND CORNER RECORD

(THIS FORM PRESCRIBED BY THE PUBLIC LAND SURVEY OFFICE, DEPARTMENT OF NATURAL RESOURCES, PURSUANT TO RCW 58.09. ALPHA-NUMERIC INDEX DIAGRAM ON THE BACK.)

FILED FOR RECORD
SKAMANIA CO. WASH.
BY *Robert Glaeser*

FEB 1 4 27 PM '94

G. Jarry
AUDITOR
GARY H. OLSON

Corner Indexing Information:

TWP 1 N RGE 5 E Corner Code C-9
(Willamette Meridian)

ADDITIONAL IDENTIFIER: (e.g., BLM designation for the corner, street intersection, plat name, block, lot, etc.)

East quarter corner of Section 5, Township 1 North, Range 5 East, Willamette Meridian.

118647

BOOK 141 PAGE 232


Skamania County Washington:

Land Surveyor Information: (or Public Officer as per RCW 58.09.090)

AUDITOR'S USE

This corner record correctly represents work performed by me or under by direction in conformance with the Survey Recording Act.

Company or agency:
Minister & Claeser Surveying, Inc.
2208 E. Evergreen Blvd.
Vancouver, WA. 98661
Phone: (206) 694-3313
Fax: (206) 694-8410



Signature *Robert W. Glaeser*

Date: 1/21/94

Seal:

Washington Plane Coordinates: N: _____ E: _____
Order: _____ Zone: _____ Datum (Date of adjustment): _____

Corner Information: Use the space below to provide the following information regarding the corner.

(1) Pertinent Corner History: The original survey was conducted by Deputy Surveyors, Lewis Van Vleet and John Newson, under Contract No. 47, dated the 23rd day of April, 1859. The survey was conducted between April 26th and April 29th, 1859. Set a quarter section post common to Sections 4 and 5.

R.P.'s were as follows:

30" diameter Fir, South 81° West, 51 Links.

4" diameter Vine Maple, South 81° East, 24 Links.

Skamania County Engineers records, shows said East quarter of Section 5, was monumented with a 5/8" Iron Rod set by County Engineer, referenced with a Iron Fence post with Tag X, 1 foot South of Iron Rod.

In August of 1973, W.F. Hagedorn conducted a survey (Book 1, page 6, of Skamania County records), and found an Iron Rod 2642.15 North of the Southeast corner of Section 5 and 2650.92 South of the Northeast corner of Section 5. Held as the East quarter corner of Section 5.

SEARCHED _____
INDEXED _____
SERIALIZED _____
FILED _____

In January of 1974, Olson Engineering conducted a survey (Book 1, page 10, of Skamania County records), and found a 5/8" Iron Rod 2614.15 North 1°11'34" East, of the Southeast corner of Section 5, and 2650.92 South 1°11'42" West of the Northeast corner of Section 5. Held as the East quarter corner of Section 5.


(2) Evidence Found at the Corner: No original evidence found. The position of this corner was calculated based on Surveys found in records of Skamania County, Surveys Book 1, page 6 and page 10. 5/8" Iron Rod was accepted as the corner based on reputation and use.

(3) Corner Perpetuation Information:

Refer to the following records of surveys:

Surveys

- Book 1, page 6
- Book 1, page 10



RCV 58.09.060 (2) requires the following information on this form: an accurate description and location, in reference to the corner position, of all monuments and accessories (a) found at the corner and (b) placed or replaced at the corner; (c) basis of bearings used to describe or locate such monuments or accessories; and (d) corollary information that may be helpful to relocate or identify the corner position.

SPACE FOR ADDITIONAL COMMENT: