

130256

BOOK 172 PAGE 534

FILED & RECORDED
SKAMIA COUNTY, WASH
BY *Laynew Fibre*

JUN 16 9 45 AM '98

Garry H. Olson
REGISTERED
GARY H. OLSON

LAND CORNER RECORD

GRANTOR/ SURVEYOR/ PUBLIC OFFICER: This corner record correctly represents work performed by me or under my direction in conformance with the Surveying Recording Act.

COMPANY OR AGENCY: LONGVIEW FIBRE COMPANY

ADDRESS:

PO BOX 667

LONGVIEW, WA 98632

GEORGE J. FORO, PLS

NO. 22330

EXP. 6-20-99



GRANTEE: PUBLIC

SEAL/SIGNATURE/DATE

LEGAL: SECTION 35

TWP: 3 NORTH

RGE: 6 EAST

CORNER CODE: Z-19

ADDITIONAL IDENTIFIER: (e.g., BLM designation, street intersection, plat, block, lot, etc.)

COUNTY: SKAMANIA

WASHINGTON PLANE COORDINATES:


N: 135568.15

ZONE: SOUTH

E: 1248337.68

ORDER: 1 DATUM (Date of adjustment): NAD 83 (1991)

CORNER INFORMATION: Provide: (1) Pertinent History, (2) Evidence Found, and (3) Corner Perpetuation Information (diagram the references; provide the date of work; and, if applicable, reference to a map of record and/or the field book/page no.) Additional space is available on the back.

(1) Pertinent History: Corner was originally established by Charles E. Sears in 1883 under contract no. 287. DNR found corner in 1947(2) Evidence Found: Found original bearing trees, now stumpsFound BT's: 42' Fir stp S40°E at 131 feet, healed scar, DNR tag 1951
18' Hemlock snag N50°W at 2015 feet, scribe visible(3) Corner Perpetuation Information: Set 3/4"x36" pipe with 2-1/2" brass cap stamped
New References: 11' Hemlock N54°E at 180 feet
13' Alder S82°W at 243 feet
Steel fence post North at 10 feet

DATE OF WORK: 10-10-97, FIELD BOOK: 97-01, PAGE: 13

This form is in compliance with the intent of RCW 65.04.045 and prescribed by the Public Land Survey Office, Department of Natural Resources - 9/96

MARK THE CORNER LOCATION BELOW AND FILL IN THE CORNER CODE BLANK ON THE OTHER SIDE.
For corners at the intersection of two lines, the corner code is the alphanumeric coordinate that corresponds to the appropriate intersection of lines.

For corners that are only on one line, the corner code is the line designation and the related line segment: i.e., a corner on line 5 between "B" and "C" is designated BC-5.

For corners that are between lines, the corner code is both line segments; i.e., a corner in the SE 1/4 of the SE 1/4 of section 18 is designated MN 4-5.

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
A																									
B																									
C																									
D																									
E																									
F																									
G																									
H																									
I																									
J																									
K																									
L																									
M																									
N																									
O																									
P																									
Q																									
R																									
S																									
T																									
U																									
V																									
W																									
X																									
Y																									
Z																									

RCW 58.09.060 (2) requires the following information on this form: an accurate description and location, in reference to the corner position, of all monuments and accessories (a) found at the corner and (b) placed or replaced at the corner; (c) basis of bearings used to describe or locate such monuments or accessories; and (d) corrobory information that may be helpful to relocate or identify the corner position.

SPACE FOR ADDITIONAL COMMENT:

NOTES:

New References have a Longview Fire Location Tag above the scribe and an 8" spike at bottom of scribe, all oriented toward monument. Bearings to references taken with hand compass having a declination of 21°e. Distances measured to spike.

The GED distances did not intersect. The monument was set at the noted distances from the found original B1S.

A 6"x6" rotten post with BNR tag was also found N15°W at 15 feet from the set monument. The post had been displaced by a down tree. We could not determine where the post had been located originally. We had to remove a portion of the down tree to set the monument. BNR tag dated 7/3/51 noted the corner N39°W at 128' from the monument. BNR tag dated 7/3/51 established at 131 feet from the found B1. The corner was