

MARK THE CORNER LOCATION BELOW AND FILL IN THE CORNER CODE BLANK ON THE OTHER SIDE.
For corners at the intersection of two lines, the corner code is the alphanumeric coordinate that corresponds to the appropriate intersection of lines.

For corners that are only on one line, the corner code is the line designation and the related line segment; i.e., a corner on line 5 between "B" and "C" is designated BC-5.

For corners that are between lines, the corner code is both line segments; i.e., a corner in the SE 1/4 of the SE 1/4 of section 18 is designated MN 4-5.

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
A																									
B					5					4					3						2				1
C																									
D																									
E																									
F																									
G								8							9						10				11
H																									12
J																									
K																									
L															16										13
M																15									
N																									
O																									
P																									
Q															21						22				24
R																									
S																									
T																									
U																									
V																									
W																									
X																									
Y																									
Z																									

RCW 58.09.060 (2) requires the following information on this form: an accurate description and location, in reference to the corner position, of all monuments and accessories (a) found at the corner and (b) placed or replaced at the corner; (c) basis of bearings used to describe or locate such monuments or accessories; and (d) corollary information that may be helpful to relocate or identify the corner position.

SPACE FOR ADDITIONAL COMMENT:

NOTES:

New References have a Longview Fibre Location Tag above the scribe and an 8" spike at bottom of scribe, all oriented toward monument. Bearings to references taken with hand compass having a declination of 21° distances measured to spike.

The GLU distances do not intersect. A new monument was set to replace the found pipe in the same location. The distance to the found spruce does not coincide with GLU. The found pipe was apparently established from the other two found BT's, as they are closer in proximity and agree with the record. Corner is approximately 70' southeast of an existing road on short ridge.