
SCALE ! - 50 FEET

KEVIN DOWD PLS 29288

COUNTY AUDITOR

FILED FOR RECORD THIS 16th DAY OF May 2001 AT 4:41 PM IN BOOK 3 AT PAGE 390 AT THE REQUEST OF WYEAST SURVEYS.

AUDITOR'S CERTIFICATE




FD. NAIL IN SIDEWALK

LEGEND:

- Ø RESET 1/2" IRON ROD WITH YELLOW PLASTIC CAP STAMPED WYEAST SURVEYS PLS 29288" IN MAY 2001
- SET 1/2" IRON ROD WITH YELLOW PLASTIC CAP STAMPED WYEAST SURVEYS PLS 29288"
- FD. MONUMENT AS NOTED
- FD. 1/2" IRON ROD WITH GLAESER CAP EXCEPT AS NOTED AS PER BOOK 2. PAGE 218 OF SURVEYS.

AS PER BOOK I, PAGE 103 OF SURVEYS



- FD. 5/8" IRON ROD AS SET OR FOUND BY BOOK I. PAGE 175 OF SURVEYS
- ⊗ FD. IRON PIPE AS PER 1957 SURVEY BY MART PERKINS COUNTY ENGINEER'S FILE 34-7.3-36.21
- CALCULATED POSITION
- () PLAT DATA
- FENCELINE

LEGAL DESCRIPTION:

LOTS 5.6 AND 7. BLOCK 2. ROSE LAWN EXTENSION

NARRATIVE:

MONUMENTS RECOVERED FROM BOOK 1. PAGE 175 OF SURVEYS. AND BOOK 2. PAGE 218 OF SURVEYS TOGETHER WITH PLAT DATA WERE HELD TO ESTABLISH THE BOUNDARIES AS SHOWN. THE PERKINS' IRON PIPES ARE SHOWN IN THEIR POSITION AS FOUND AND WERE NOT HELD IN BOUNDARY ESTABLISHMENT.

NARRATIVE FOR AMENDMENT:

DURING THE COURSE OF PERFORMING A SURVEY ON AN ADJOINING PARCEL IT WAS DISCOVERED THAT THE PLAT DISTANCE FOR THE WEST LINE OF BLOCK 4 AND THE PLAT BEARING FOR THE NORTHERLY LINE OF BLOCK 2 AS USED FOR THE SURVEY OF LOTS 5.6 AND 7 OF BLOCK 2 WERE INCORRECT. THE MISTAKE OCCURED DUE TO THE ILLEGIBILITY OF THE PLAT. LOT AND BLOCK CORNERS WERE RECALCULATED USING THE CORRECT PLAT DATA. THE IRON RODS ON THE NORTHERLY LINE OF LOT 7. BLOCK 2 WERE RESET AS PER THE RECALCULATIONS.

AMENDED RECORD OF SURVEY

AMENDS RECORD OF SURVEY RECORDED IN BOOK 3 OF SURVEYS AT PAGE 332

LOTS 5.6 AND 7. BLOCK 2 ROSE LAWN EXTENSION SITUATED IN THE SOUTHEAST QUARTER
OF SECTION 36
T3 NORTH. R7 EAST. W.M.
IN THE CITY OF STEVENSON
SKAMANIA COUNTY. WASHINGTON

FOR: LOWELL ASH



WYEAST SURVEYS KEVIN DOWD 4399 WOODWORTH DR MT. HOOD. OR 97041 (541) 352-6065

