

Auditor's File Number 20044152308, Tax Lot 02-07-19-0-0-0902

Deed Bk. 27 Pg. 319, Bonneville Power Add., Right of Way owned in Fee Simple.

Property Deed References Used

Deed Bk. 145, Pg. 33, Tax Lot 02-07-19-0-0-0902 Deed Bk. 140 Pg. 598, Tax Lot 02-07-19-0-0-1100

Deed Bk. 125 Pg. 582, Tax Lot 02-07-20-0-0-1000

Deed Bk. 161 Pg. 770, Tax Lot 02-07-19-0-0-1101 Deed Bk. 169 Pg. 601, Tax Lot 02-07-19-0-0-0903

Point No. Description of Found Monuments

- 5/8" iron rebar with aluminum cap stamped \bigcirc 2 "SKAMANIA COUNTY ENG", flush, See Auditor's File Number 13206, Survey Bk. 3 Pg. 271, held.
- 5/8" iron rebar with illegible yellow plastic cap, \bigcirc 3 1.5 below grade, See Auditors File Number 95883, Short Plat Bk. 3 Pg. 48. held.
- 1/2" iron rod with brass cap stamped "Corps of Engineer—Army LS Survey Mark (15)19/DLC 1976 83 Agency" set in 4" by 4" concrete, flush, See Auditors File Number 95883, Short Plat Bk. 3 Pg. 48, held.
- 5/8" iron rebar with aluminum cap stamped (17) "SKAMANIA COUNTY ENG", flush, See Auditor's File Number 13206, Survey Bk. 3 Pg. 271, not held. Rebar is offline N 28-38'-18" W, 0.75'.
- 5/8" iron rebar with a red plastic cap stamped "LS 29959" 25 leaning southwesterly, 1.0' above grade. See Survey Bk. 3 Pg. 186, not held.
- 5/8" iron rebar with a red plastic cap stamped "LS 29959" 30 flush, See Survey Bk. 3 Pg. 186, held.
- 5/8" iron rebar with no cap, disturbed, bent westerly, (200) shot center of spin, 0.1 below grade, See Auditor's File Number 95883, Bk. 3 Pg. 48, held.
- 1/2" iron rod with brass cap stamped "Corps of Engineer—Army LS survey mark 202 NB 171 1977 83 Agency" set in 4" by 4" concrete, flush, See Auditors File Number 94016, Short Plat Bk. 3 Pg. 52, held.
- 1/2" iron rod with brass cap stamped "Corps of Engineer—Army LS survey mark (205) NB 169 1977 83 Agency" set in 4" by 4" concrete, flush See Auditors File Number 94016, Short Plat Bk. 3 Pg. 52, held.
- 5/8" iron rebar with no cap, 0.3' below grade. See Auditor's File Number 95883, Bk. 3 Pg. 48, not held. (208) Rebar bears N33-55-43"W, 0.56' from calculated point.
- 5/8" iron rebar, 0.3 below grade, See Auditor's File Number 95883, Bk. 3 Pg. 48, not held. (210) Rebar bears N24-57-11W, 0.47' from calculated point.
- (211)5/8" iron rebar with aluminum cap stamped "SKAMANIA COUNTY ENG", 0.2 above grade, See Auditor's File Number 13206, Survey Bk. 3 Pg. 271, held.
- (214) 5/8" iron rebar with aluminum cap stamped "SKAMANIA COUNTY ENG", 0.5 above grade, See Auditor's File Number 13206, Survey Bk. 3 Pg. 271, held for line only. Rebar bears N0-55-15E, 0.50' from calculated point.
- 5/8" iron rebar, severely disturbed, bent easterly. (216) See Survey Bk. 3 Pg. 171, not held.
- (217)5/8" iron rebar with aluminum cap stamped "SKAMANIA COUNTY ENG", 0.3 above grade, See Auditor's File Number 13206, Survey Bk. 3 Pg. 271, held.
- (218) 5/8" iron rebar with aluminum cap stamped "SKAMANIA COUNTY ENG", 0.3 above grade, See Auditor's File Number 13206, Survey Bk. 3 Pg. 271, held.
- 5/8" iron rebar, disturbed, bent southwesterly. (219) See Survey Bk. 3 Pg. 171, not held. Rebar bears N21-13-31E, 0.58' from calculated point.
- 5/8" iron rebar with no cap, disturbed, bent westerly, See Auditor's File Number 95883, Bk. 3 Pg. 48, not held. 921 Rebar bears N67-18-48W, 0.46' from calculated point.

Narrative:

The purpose of this survey is to perform a lot line adjustment between tax lot 902 and Tax Lot 1100 and monument the new lot corners.

The south boundary of the BPA right of way in Deed Bk. 27 Page 320 was established by holding monumentation along that line in Survey Book 3 Page 271. The section line between sections 19 and 20 was established by holding monumentation shown in Survey Book 3 Page 186 and Survey Book 3 Page 271. The south line of Tax lot 1100 per Deed Book 140 Page 599 was established by holding the south line of natural pipe line easement as calculated in Short Plat Book 3 Page 48 (Longview Fibre Short Plat) and Short Plat Book 3 Page 251 (Peterson Industrial Park Short Plat). The west line of the Hamilton D.L.C. was established holding Corps of Engineers monument NB 169 and Corps of Engineers monument 19/DLC 40-1 which were set on the Hamilton DLC line. Hamilton Creek County Road was established holding Longview Fibre Co. Short Plat.

Survey and Short Plat References Used

Longview Fibre Co. Short Plat, Auditor's File Number 95883, Short Plat Book 3 Page 48. Peterson Industrial Short Plat, Auditor's File Number 120897, Short Plat Book 3 Page 251. Survey for Skamania County by Richard Lang, Auditor's File Number 13026, Survey Book 3 Page 271. Survey for Richard Beckman by Robert Dean, Auditor's File Number 121973, Survey Book 3, Page 186 Port of Skamania Short Plat, Auditor's File Number 120970, City Book T Page 93 Survey for Port of Skamania by Robert Glaeser, Auditor's File Number 120969, Survey Book 3, Page 171 Fifth Addition to the Plats of Relocated North Bonneville, Auditor's File Number 94016, Short Plat Book 3 Page 52

Sheet 2 of 3

Tax lot 1100 and Tax lot 902 located in Hamilton D.L.C., Section, 19, Township 2 North, Range 7 East of the Willamette Meridian Skamania County, Washington

LOT LINE ADJUSMENT LOCATION:

SURVEY FOR:

Board of Commissioners of Skamania County

SURVEY BY: Todd Matz P.O. Box 790 Stevenson, Wa. 98648

DATE: 10/15/07







