1/4 S 20/28
FD. Skamania Co. mon box
in the c/l of Monaghan & south
edge of Hot Springs Ave.
this is not in the c/l of the existing rd.
Fk 1-2, 4 S28 3/08


0

Fd. IR w/pc F/bk 1-6 S28 3/08

In Skamania County for Wayne & Susanne Neece Survey is Located in NE 1/4 SW 1/4 Sec. 28 T3N R8E W.M.

This map correctly represents a survey made by me or under my direction during the period of Oct., 2007 through Jan 23, 2008; in conformance with the requirements of the Survey Recording Act at the request of Wayne & Susanne Neece

Jan. 24, 2008 Dennis Peoples Licensed Land Surveyor 25552 WA, 2325 OR Date



a's name: Wayne & Susanne Neece

scription of total parcel Lot 2 of G & D Short Plat

References: GLO notes, deeds, surveys of record book and page or AF#.

Equipment: 6" Topcon Total Station or 3" Leica Total Station, closed loop, Calibrated March 2007, closed loop by Least Squares or Compass Rule, 1/13.7K 0.06'

1. I was asked to see if the new fence line running along the north line of Lot 2 was over the line & to see if the fence corner at the northeast corner of Lot 2 of G & D short plat was over the line as well.

2. After running a traverse from the 1/4 between S 21/S 28 and tieing into previous work within 0.06' I tied the controling corners around the G & D Short Plat from one point. I found that the north West corner and the southeast of Lot 2 and the northeast corners fit the calculated

3. I drove a nail in the center of the existing fence posts at the northeast & northwest corners of lot 2. The nail at the northwest corner is S38`00'53"E, 0.57' of the actual corner. Therefore niether the fence corner at the Northeast or at the northwest is over actual property line.

4. The nail in the post at the northeast corner is S6`13'23"W, 0.32' which would place that fence corner at the northeast corner of lot 2 also south of the

actual property line.

5. I was then asked to mark the actual line so the wooden posts could be removed and any conc. to be removed from the post so that the conc. around the post would not be encroaching 0.10-.20'. I staked that line in last portion of Jan. 2008. The posts were moved and thus no encroachment exist. I was not asked to check this.

6. I did not set the missing corner at the northeast corner of lot 2 because it would be close to the existing fence corner. I therefore held a point on the north line of lot 2 and set an offset point 2.00' east of the actual point.

7_ day of February 200 8_, at \$30.4 and recorded 13 page ____ 2008168917 at the request of D2AB Surveying.

Aud. #

Fd. IR w/pc F/bk 1-7 S28 3/08