


SE CORNER SECTION 24-T3N-R7E (SC): FOUND AND ACCEPTED A 1" IRON PIPE WITH 3" SKAMANIA COUNTY BRASS CAP AS PER REFERENCE SURVEY # 5 (2015). CORNER FALLS ON PRIVATE PROPERTY SO NEW REFERENCES WERE NOT ESTABLISHED.



SW CORNER SECTION 24-T3N-R71/2E (CC): FOUND AND ACCEPTED A 1" IRON PIPE WITH 3" SKAMANIA COUNTY BRASS CAP AS PER REFERENCE SURVEY # 5 (2015). THE AMENDED CLOSING CORNER POSITION BEARS N89'23'04"W 8.085' FROM SAID MONUMENT. CORNER FALLS ON PRIVATE PROPERTY SO NEW REFERENCES WERE NOT ESTABLISHED.



FOUND 1" IRON PIPE WITH 1 1/2" BRASS CAP AS ESTABLISHED ON REFERENCE SURVEY # 5 ON THE NORTHERLY TOP BANK OF WOLF CREEK (2015). FOUND MONUMENT IS 0.68' WEST OF LINE AS DERIVED BY THIS SURVEY. NEW ACCESSORIES:



E 1/4 CORNER SECTION 24-T3N-R7E (SC): FOUND AND ACCEPTED A 1" IRON PIPE WITH 3" SKAMANIA COUNTY BRASS CAP AS PER REFERENCE SURVEY # 6 (2015).




FOUND ACCESSORY: - 23" FIR SNAG WITH SPIKE & STATE TAG S30'W 15.86' NEW ACCESSORY:

- 7" CEDAR S24'E 12.20' TO 40D SPIKE



W 1/4 CORNER SECTION 24-T3N-R71/2E (CC): FOUND A 1" IRON PIPE WITH 1 1/2" BRASS CAP AS PER REFERENCE SURVEY # 5 (2015). THE AMENDED CLOSING CORNER POSITION BEARS S89'19'39"E 0.68' FROM SAID MONUMENT. NEW





NE CORNER SECTION 24-T3N-R7E (SC): POSITION OF A 1" IRON PIPE WITH 3" SKAMANIA COUNTY BRASS CAP AS PER REFERENCE SURVEY # 6, NOT VISITED BY THIS SURVEY.



NW CORNER SECTION 24-T3N-R71/2E (CC): FOUND AND ACCEPTED A 1" IRON PIPE WITH 3" SKAMANIA COUNTY BRASS CAP AS PER REFERENCE SURVEYS # 5 & 6 (2015).



NW CORNER SECTION 24-T3N-R71/2E (AMCC): FOUND AND ACCEPTED THE CONCRETE MONUMENT WITH 3" DNR BRASS CAP AS ESTABLISHED ON REFERENCE SURVEY # 6 (2015). HELD FOR BASIS OF BEARINGS.



NW CORNER GOVERNMENT LOT 2 IN SECTION 24-T3N-R71/2E: FOUND THE 1" IRON PIPE WITH 1 1/2" BRASS CAP AS ESTABLISHED ON REFERENCE SURVEY # 5 (2015). THIS PIPE WAS HELD TO CONTROL THE WEST LINE OF GOVERNMENT LOTS 2 AND 5. AS DEPICTED ON DETAIL # 4 ON PAGE 1 THIS PIPE FALLS 1.53' NORTH OF THE NORTH LINE OF SECTION 24. THIS SURVEY DID NOT ESTABLISH A MONUMENT AT THE AMENDED POSITION.



SE CORNER GOVERNMENT LOT 12 IN SECTION 13-T3N-R71/2E: FOUND AND ACCEPTED THE CONCRETE MONUMENT WITH 3" DNR BRASS CAP AS ESTABLISHED ON REFERENCE SURVEY # 6 (2015).



N 1/4 CORNER SECTION 24-T3N-R71/2E: POSITION OF THE 1" IRON PIPE WITH 1 1/2" BRASS CAP AS ESTABLISHED ON REFERENCE SURVEY # 5 AND RECOVERED ON REFERENCE SURVEY # 6 CALCULATED AS PER REFERENCE SURVEY # 6 (NOT VISITED).




NE CORNER SECTION 24-T3N-R71/2E (SC): FOUND AND ACCEPTED THE 1" IRON PIPE WITH 1 1/2" BRASS CAP AS ESTABLISHED TO PERPETUATE A SINGLE PROPORTION POSITION RECOVERED IN 1967 ON REFERENCE SURVEY # 5 AND LATER RECOVERED ON REFERENCE SURVEY # 6 (2015). ALSO FOUND THE CONCRETE MONUMENT WITH 3" DNR BRASS CAP ESTABLISHED AS AN AMCC ON REFERENCE SURVEY # 6 BEARING S89'02'42"E 10.48' FROM SAID CORNER (2015). DUE TO THE FACT THAT THE 1893 GLO SURVEY BY RICHARDSON RESURVEYED THE EAST BOUNDARY OF T3N R71/2E (SEE RS # 2) AND MEASURED THROUGH ALL OF THE CORNERS PREVIOUSLY ESTABLISHED BY THE 1878 GLO SURVEY BY MCCORMACK FOR T3N R8E (SEE RS # 1) ALL ESTABLISHED CORNERS ALONG THIS LINE ARE STANDARD AND THE CREATION OF AN AMENDED CLOSING CORNER IS A QUESTIONABLE




NW CORNER SECTION 19-T3N-R8E (SC): FOUND AND ACCEPTED THE CONCRETE MONUMENT WITH 3" DNR BRASS CAP AS ESTABLISHED ON REFERENCE SURVEY # 6 (2015).



E 1/4 CORNER SECTION 24-T3N-R71/2E (SC): FOUND AND ACCEPTED THE 1" IRON PIPE WITH 1 1/2" BRASS CAP AS ESTABLISHED IN 1967 FROM TWO FOUND ORIGINAL BEARING TREES AND A GLO CREEK CALL AS PER REFERENCE SURVEY # 5 (2015). FOUND ACCESSORIES:







W 1/4 CORNER SECTION 19-T3N-R8E (SC): FOUND AND ACCEPTED THE 1" ALUMINUM PIPE WITH 0.8' VISIBLE AS ESTABLISHED BY LONGVIEW FIBRE CO. AND AS NOTED ON REFERENCE SURVEY # 7 (2015). FOUND ACCESSORIES:

- 36" FIR S60'E 15.00' TO 40D SPIKE

- 25" NOBLE FIR S25'W 22.50' TO 40D SPIKE



C 1/4 CORNER SECTION 24-T3N-R71/2E: FOUND AND ACCEPTED THE 1" IRON PIPE WITH 1 1/2" BRASS CAP AS ESTABLISHED IN 1967 ON REFERENCE SURVEY # 5 (2015).

FOUND ACCESSORY: - 20" FIR WITH HEALED FACE N82'E 17.90' TO 40D SPIKE

- 12" FIR NO8'W 11.00' TO 40D SPIKE



CS 1/16TH CORNER SECTION 24-T3N-R71/2E: FOUND AND ACCEPTED THE 1" IRON PIPE WITH 1 1/2" BRASS CAP AS ESTABLISHED IN 1967 ON REFERENCE SURVEY # 5 (2015).

FOUND ACCESSORY: - 34" FIR WITH HEALED FACE N45'E 17.26' TO 40D SPIKE NEW ACCESSORY:

- 15" FIR S56'W 10.69' TO 40D SPIKE



S 1/4 CORNER SECTION 24-T3N-R71/2E: FOUND AND ACCEPTED THE 1" IRON PIPE WITH 1 1/2" BRASS CAP AS ESTABLISHED IN 1967 BY SINGLE PROPORTION ON REFERENCE SURVEY # 5 (2015). NO ACCESSORIES FOUND OR ESTABLISHED.



CN 1/16TH CORNER SECTION 24-T3N-R71/2E: FOUND AND ACCEPTED THE 1" IRON PIPE WITH 1 1/2" BRASS CAP AS ESTABLISHED IN 1967 ON REFERENCE SURVEY # 5 (2015).

FOUND ACCESSORIES:

- 38" FIR WITH STATE TAG S66'W 11.45' TO 40D SPIKE - 6" ALDER WITH STATE TAG S60'E 12.32' TO 40D SPIKE
- 8" HEMLOCK WITH STATE TAG N21'E 13.61' TO 40D SPIKE



NW CORNER GOVERNMENT LOT 5 IN SECTION 24-T3N-R71/2E: AT THE POSITION DEPICTED HEREON THIS SURVEY SET A 5/8" REBAR WITH 3" ALUMINUM CAP STAMPED PER THE BLM MANUAL (2015) AND ESTABLISHED THE FOLLOWING ACCESSORIES:

- 24" FIR S23"E 16.51' TO 40D SPIKE - 14" FIR S38'W 4.34' TO 40D SPIKE



SW CORNER GOVERNMENT LOT 5 IN SECTION 24-T3N-R71/2E: THIS SURVEY FOUND THAT THE MONUMENT ESTABLISHED ON REFERENCE SURVEY # 5 HAD BEEN DESTROYED. AT THE POSITION DEPICTED HEREON THIS SURVEY SET A 5/8" REBAR WITH 3" ALUMINUM CAP STAMPED PER THE BLM MANUAL (2015). THIS CORNER FALLS WITHIN THE BPA RIGHT OF WAY AND NO SUITABLE TREES WERE AVAILABLE AS ACCESSORIES WITHIN A REASONABLE DISTANCE.




NW CORNER GOVERNMENT LOT 11 IN SECTION 24-T3N-R71/2E: FOUND AND ACCEPTED THE 1" IRON PIPE WITH 1 1/2" BRASS CAP AS ESTABLISHED IN 1967 ON REFERENCE SURVEY # 5 (2015).

FOUND ACCESSORY: - 27" FIR STUMP WITH PARTIAL SCRIBE N20'E 5.80' **NEW ACCESSORIES:** 

- 12" CEDAR N72°E 7.70' TO 40D SPIKE - 9" CEDAR SO9'E 4.07' TO 40D SPIKE

NOTE: THE STANDARD NEW ACCESSORY ESTABLISHED BY THIS SURVEY HAS A 40D SPIKE IN CENTER SIDE, 4 NOTCHES AND AN ALUMINUM TAG FACING THE CORNER.

Dependent resurvey of the north line of the Southeast Quarter and portions of Government Lots 5, 6, 7, 8, 9 and 10, all in Section 24, Township 3 North, Range 7 1/2 E, W.M. in Skamania County, Washington (Page 2 of 2 Pages)



Scale none

Sheet 2 of 2

