

E/L1/6 COR.
Fd. 5/8" R/C LS-9025 W/6"
steel reference post North 1.0'.
(See SR-1/2)

FOUND REFERENCES
-8" ALDER STUMP W/ SPIKE
-10" W-18.9'
-20" FIR W/ SPIKE @ TAG
-56" E-11.7'
-20" FIR W/ SPIKE @ TAG
-58" W-27.4'

A DEPENDENT SURVEY for
Weyerhaeuser Columbia Timberlands
Indexed as being a portion of the:
SECTION 8, and the E.1/2 of SECTION 7, T2N R5E, W.M.
as situated within
SKAMANIA COUNTY, WASHINGTON

L1/4 COR.
Calculated per
SR-2
S.6
S.7
N 89°03'09" W - 2614.56'
1307.28'
(SAME AS SR-2)
1307.28'
(SAME AS SR-2)
SECTION COR.
Calculated per
SR-1/2
S.6
S.5
N 89°52'38" E - 5216.28'
(N89°52'38"E-5216.28'-SR-1)
(2608.74'-SR-1)
2608.14'

Weyerhaeuser Columbia Timberlands
265.87 AC ±

SECTION COR.
Fd. 3/4" IP W/2-1/2" stamped
brass cap. (Added 6" steel
reference post w/10g,
South-2.0') (See SR-1)
FOUND REFERENCES
-30" FIR STUMP W/ SPIKE
-29" W-10.6'
-24" FIR STUMP W/ SPIKE
-176" E-46.9'
-42" FIR STUMP
-508" E-64.9'
-42" FIR STUMP
-568" W-6.0'

BASIS OF BEARING
BETWEEN FOUND CORNERS
ON THE EAST LINE OF
SECTION 8.
SEE SR-1

C/L1/6 COR.
Calculated per
SR-2
N 02°06'27" E - 2618.12'
(SAME AS SR-2)
1309.06'
(SAME AS SR-2)
S 89°04'23" E
1318.76'
NE.1/16 COR.
Fd. 5/8" R/C
LS-9025
(See SR-1/2)
FOUND REFERENCES
-5" FIR STUMP W/ TAG
-564" W-12.0'
-16" ALDER STUMP
-566" E-18.9'

Weyerhaeuser Columbia Timberlands
265.87 AC ±

SECTION COR.
Calculated per
SR-1/2
S.6
S.5
N 89°52'38" E - 5216.28'
(N89°52'38"E-5216.28'-SR-1)
(2608.74'-SR-1)
2608.14'

Weyerhaeuser Columbia Timberlands
265.87 AC ±

SECTION COR.
Fd. 3/4" IP W/2-1/2" stamped
brass cap. (Added 6" steel
reference post w/10g,
South-2.0') (See SR-1)
FOUND REFERENCES
-30" FIR STUMP W/ SPIKE
-29" W-10.6'
-24" FIR STUMP W/ SPIKE
-176" E-46.9'
-42" FIR STUMP
-508" E-64.9'
-42" FIR STUMP
-568" W-6.0'

C/L1/4 COR.
Calculated per
SR-2
N 01°37'11" E - 2614.53'
(SAME AS SR-2)
1329.58'
(SAME AS SR-2)
S 89°05'39" E
1329.58'
(SAME AS SR-2)
CE.1/16 COR.
Calculated per
SR-2
N 01°38'04" E - 1308.39'
(N01°37'11"E-1308.40'-SR-2)
(1316.43'-SR-2)
S 89°04'27" E
1318.09'
(N89°04'25"W)
(1316.43'-SR-2)

Weyerhaeuser Columbia Timberlands
265.87 AC ±

SECTION COR.
Calculated per
SR-1/2
S.6
S.5
N 89°52'38" E - 5216.28'
(N89°52'38"E-5216.28'-SR-1)
(2608.74'-SR-1)
2608.14'

Weyerhaeuser Columbia Timberlands
265.87 AC ±

SECTION COR.
Fd. 3/4" IP W/2-1/2" stamped
brass cap. (Added 6" steel
reference post w/10g,
South-2.0') (See SR-1)
FOUND REFERENCES
-30" FIR STUMP W/ SPIKE
-29" W-10.6'
-24" FIR STUMP W/ SPIKE
-176" E-46.9'
-42" FIR STUMP
-508" E-64.9'
-42" FIR STUMP
-568" W-6.0'

C/L1/4 COR.
Calculated per
SR-2
N 01°37'11" E - 2614.53'
(SAME AS SR-2)
1329.58'
(SAME AS SR-2)
S 89°05'39" E
1329.58'
(SAME AS SR-2)
CE.1/16 COR.
Calculated per
SR-2
N 01°38'04" E - 1308.39'
(N01°37'11"E-1308.40'-SR-2)
(1316.43'-SR-2)
S 89°04'27" E
1318.09'
(N89°04'25"W)
(1316.43'-SR-2)

Weyerhaeuser Columbia Timberlands
265.87 AC ±

SECTION COR.
Calculated per
SR-1/2
S.6
S.5
N 89°52'38" E - 5216.28'
(N89°52'38"E-5216.28'-SR-1)
(2608.74'-SR-1)
2608.14'

Weyerhaeuser Columbia Timberlands
265.87 AC ±

SECTION COR.
Fd. 3/4" IP W/2-1/2" stamped
brass cap. (Added 6" steel
reference post w/10g,
South-2.0') (See SR-1)
FOUND REFERENCES
-30" FIR STUMP W/ SPIKE
-29" W-10.6'
-24" FIR STUMP W/ SPIKE
-176" E-46.9'
-42" FIR STUMP
-508" E-64.9'
-42" FIR STUMP
-568" W-6.0'

C/L1/4 COR.
Calculated per
SR-2
N 01°37'11" E - 2614.53'
(SAME AS SR-2)
1329.58'
(SAME AS SR-2)
S 89°05'39" E
1329.58'
(SAME AS SR-2)
CE.1/16 COR.
Calculated per
SR-2
N 01°38'04" E - 1308.39'
(N01°37'11"E-1308.40'-SR-2)
(1316.43'-SR-2)
S 89°04'27" E
1318.09'
(N89°04'25"W)
(1316.43'-SR-2)

Weyerhaeuser Columbia Timberlands
265.87 AC ±

SECTION COR.
Calculated per
SR-1/2
S.6
S.5
N 89°52'38" E - 5216.28'
(N89°52'38"E-5216.28'-SR-1)
(2608.74'-SR-1)
2608.14'

Weyerhaeuser Columbia Timberlands
265.87 AC ±

SECTION COR.
Fd. 3/4" IP W/2-1/2" stamped
brass cap. (Added 6" steel
reference post w/10g,
South-2.0') (See SR-1)
FOUND REFERENCES
-30" FIR STUMP W/ SPIKE
-29" W-10.6'
-24" FIR STUMP W/ SPIKE
-176" E-46.9'
-42" FIR STUMP
-508" E-64.9'
-42" FIR STUMP
-568" W-6.0'

C/L1/4 COR.
Calculated per
SR-2
N 01°37'11" E - 2614.53'
(SAME AS SR-2)
1329.58'
(SAME AS SR-2)
S 89°05'39" E
1329.58'
(SAME AS SR-2)
CE.1/16 COR.
Calculated per
SR-2
N 01°38'04" E - 1308.39'
(N01°37'11"E-1308.40'-SR-2)
(1316.43'-SR-2)
S 89°04'27" E
1318.09'
(N89°04'25"W)
(1316.43'-SR-2)

Weyerhaeuser Columbia Timberlands
265.87 AC ±

SECTION COR.
Calculated per
SR-1/2
S.6
S.5
N 89°52'38" E - 5216.28'
(N89°52'38"E-5216.28'-SR-1)
(2608.74'-SR-1)
2608.14'

Weyerhaeuser Columbia Timberlands
265.87 AC ±

SECTION COR.
Fd. 3/4" IP W/2-1/2" stamped
brass cap. (Added 6" steel
reference post w/10g,
South-2.0') (See SR-1)
FOUND REFERENCES
-30" FIR STUMP W/ SPIKE
-29" W-10.6'
-24" FIR STUMP W/ SPIKE
-176" E-46.9'
-42" FIR STUMP
-508" E-64.9'
-42" FIR STUMP
-568" W-6.0'

C/L1/4 COR.
Calculated per
SR-2
N 01°37'11" E - 2614.53'
(SAME AS SR-2)
1329.58'
(SAME AS SR-2)
S 89°05'39" E
1329.58'
(SAME AS SR-2)
CE.1/16 COR.
Calculated per
SR-2
N 01°38'04" E - 1308.39'
(N01°37'11"E-1308.40'-SR-2)
(1316.43'-SR-2)
S 89°04'27" E
1318.09'
(N89°04'25"W)
(1316.43'-SR-2)

Weyerhaeuser Columbia Timberlands
265.87 AC ±

SECTION COR.
Calculated per
SR-1/2
S.6
S.5
N 89°52'38" E - 5216.28'
(N89°52'38"E-5216.28'-SR-1)
(2608.74'-SR-1)
2608.14'

Weyerhaeuser Columbia Timberlands
265.87 AC ±

SECTION COR.
Fd. 3/4" IP W/2-1/2" stamped
brass cap. (Added 6" steel
reference post w/10g,
South-2.0') (See SR-1)
FOUND REFERENCES
-30" FIR STUMP W/ SPIKE
-29" W-10.6'
-24" FIR STUMP W/ SPIKE
-176" E-46.9'
-42" FIR STUMP
-508" E-64.9'
-42" FIR STUMP
-568" W-6.0'

C/L1/4 COR.
Calculated per
SR-2
N 01°37'11" E - 2614.53'
(SAME AS SR-2)
1329.58'
(SAME AS SR-2)
S 89°05'39" E
1329.58'
(SAME AS SR-2)
CE.1/16 COR.
Calculated per
SR-2
N 01°38'04" E - 1308.39'
(N01°37'11"E-1308.40'-SR-2)
(1316.43'-SR-2)
S 89°04'27" E
1318.09'
(N89°04'25"W)
(1316.43'-SR-2)

Weyerhaeuser Columbia Timberlands
265.87 AC ±

SECTION COR.
Calculated per
SR-1/2
S.6
S.5
N 89°52'38" E - 5216.28'
(N89°52'38"E-5216.28'-SR-1)
(2608.74'-SR-1)
2608.14'

Weyerhaeuser Columbia Timberlands
265.87 AC ±

SECTION COR.
Fd. 3/4" IP W/2-1/2" stamped
brass cap. (Added 6" steel
reference post w/10g,
South-2.0') (See SR-1)
FOUND REFERENCES
-30" FIR STUMP W/ SPIKE
-29" W-10.6'
-24" FIR STUMP W/ SPIKE
-176" E-46.9'
-42" FIR STUMP
-508" E-64.9'
-42" FIR STUMP
-568" W-6.0'

C/L1/4 COR.
Calculated per
SR-2
N 01°37'11" E - 2614.53'
(SAME AS SR-2)
1329.58'
(SAME AS SR-2)
S 89°05'39" E
1329.58'
(SAME AS SR-2)
CE.1/16 COR.
Calculated per
SR-2
N 01°38'04" E - 1308.39'
(N01°37'11"E-1308.40'-SR-2)
(1316.43'-SR-2)
S 89°04'27" E
1318.09'
(N89°04'25"W)
(1316.43'-SR-2)

Weyerhaeuser Columbia Timberlands
265.87 AC ±

SECTION COR.
Calculated per
SR-1/2
S.6
S.5
N 89°52'38" E - 5216.28'
(N89°52'38"E-5216.28'-SR-1)
(2608.74'-SR-1)
2608.14'

Weyerhaeuser Columbia Timberlands
265.87 AC ±

SECTION COR.
Fd. 3/4" IP W/2-1/2" stamped
brass cap. (Added 6" steel
reference post w/10g,
South-2.0') (See SR-1)
FOUND REFERENCES
-30" FIR STUMP W/ SPIKE
-29" W-10.6'
-24" FIR STUMP W/ SPIKE
-176" E-46.9'
-42" FIR STUMP
-508" E-64.9'
-42" FIR STUMP
-568" W-6.0'

C/L1/4 COR.
Calculated per
SR-2
N 01°37'11" E - 2614.53'
(SAME AS SR-2)
1329.58'
(SAME AS SR-2)
S 89°05'39" E
1329.58'
(SAME AS SR-2)
CE.1/16 COR.
Calculated per
SR-2
N 01°38'04" E - 1308.39'
(N01°37'11"E-1308.40'-SR-2)
(1316.43'-SR-2)
S 89°04'27" E
1318.09'
(N89°04'25"W)
(1316.43'-SR-2)

Weyerhaeuser Columbia Timberlands
265.87 AC ±

SECTION COR.
Calculated per
SR-1/2
S.6
S.5
N 89°52'38" E - 5216.28'
(N89°52'38"E-5216.28'-SR-1)
(2608.74'-SR-1)
2608.14'

Weyerhaeuser Columbia Timberlands
265.87 AC ±

SECTION COR.
Fd. 3/4" IP W/2-1/2" stamped
brass cap. (Added 6" steel
reference post w/10g,
South-2.0') (See SR-1)
FOUND REFERENCES
-30" FIR STUMP W/ SPIKE
-29" W-10.6'
-24" FIR STUMP W/ SPIKE
-176" E-46.9'
-42" FIR STUMP
-508" E-64.9'
-42" FIR STUMP
-568" W-6.0'

C/L1/4 COR.
Calculated per
SR-2
N 01°37'11" E - 2614.53'
(SAME AS SR-2)
1329.58'
(SAME AS SR-2)
S 89°05'39" E
1329.58'
(SAME AS SR-2)
CE.1/16 COR.
Calculated per
SR-2
N 01°38'04" E - 1308.39'
(N01°37'11"E-1308.40'-SR-2)
(1316.43'-SR-2)
S 89°04'27" E
1318.09'
(N89°04'25"W)
(1316.43'-SR-2)

Weyerhaeuser Columbia Timberlands
265.87 AC ±

SECTION COR.
Calculated per
SR-1/2
S.6
S.5
N 89°52'38" E - 5216.28'
(N89°52'38"E-5216.28'-SR-1)
(2608.74'-SR-1)
2608.14'

Weyerhaeuser Columbia Timberlands
265.87 AC ±

SECTION COR.
Fd. 3/4" IP W/2-1/2" stamped
brass cap. (Added 6" steel
reference post w/10g,
South-2.0') (See SR-1)
FOUND REFERENCES
-30" FIR STUMP W/ SPIKE
-29" W-10.6'
-24" FIR STUMP W/ SPIKE
-176" E-46.9'
-42" FIR STUMP
-508" E-64.9'
-42" FIR STUMP
-568" W-6.0'


C/L1/4 COR.
Calculated per
SR-2
N 01°37'11" E - 2614.53'
(SAME AS SR-2)
1329.58'
(SAME AS SR-2)
S 89°05'39" E
1329.58'
(SAME AS SR-2)
CE.1/16 COR.
Calculated per
SR-2
N 01°38'04" E - 1308.39'
(N01°37'11"E-1308.40'-SR-2)
(1316.43'-SR-2)
S 89°04'27" E
1318.09'
(N89°04'25"W)
(1316.43'-SR-2)

Weyerhaeuser Columbia Timberlands
265.87 AC ±

SECTION COR.
Calculated per
SR-1/2
S.6
S.5
N 89°52'38" E - 5216.28'
(N89°52'38"E-5216.28'-SR-1)
(2608.74'-SR-1)
2608.14'

Weyerhaeuser Columbia Timberlands
265.87 AC ±

SECTION COR.
Fd. 3/4" IP W/2-1/2" stamped
brass cap. (Added 6" steel
reference post w/10g,
South-2.0') (See SR-1)
FOUND REFERENCES
-30" FIR STUMP W/ SPIKE
-29" W-10.6'
-24" FIR STUMP W/ SPIKE
-176" E-46.9'
-42" FIR STUMP
-508" E-64.9'
-42" FIR STUMP
-568" W-6.0'



SURVEYOR'S CERTIFICATE

This map correctly represents a survey made by me or under my direction, in conformance with the requirements of the Survey Recording Act of 1973, at the request of Weyerhaeuser Columbia Timberlands

in March, 20 17.

Phillip R. Gustin
Phillip R. Gustin, P.L.S.
Certificate no. 37,529

Date signed: 5/15/2017

HAMPSTUR CORPORATION

Calculated by: PRG/TLG

Checked by: PRG/CJH

Drawn by: TLG


Completion date: 4/6/2017

Field Book no.: PS-789

Drawing No.: 17-619.DWG

HAMPSTUR JOB no.: 17-619

Sheet no. 1 of 1



SURVEY REFERENCE (SR)

- 1) 1982 SURVEY BY J. OLSON, LS-9025, BK.2 PAGES 100-104
- 2) 1993 SURVEY BY J. OLSON, LS-9025, BK.3 PAGE 113

AUDITOR'S CERTIFICATE

Filed for record this 18 day of May, 2017
at 9:32 A.M. in BOOK of SURVEYS, of
PAGE 1, of the request of HAMPSTUR CORPORATION,
Robert J. Waymire
COUNTY AUDITOR

P.O. Box 368
Kelso, Washington 98626
Phone: (360) 423-8166