RETURN TO: Erielle Lamb 987 McClellan Rd Vancouver, WA 98661

Skamania County, WA Total:\$0.00 2025-000598 LCR 04/30/2025 00-25 AM Pgs=3

Request of: ERIELLE LAMB

00021086202500005980030031


LAND CORNER RECORD

THIS FORM IS FOR RECORDING A PLSS CORNER MONUMENT AND ACCESSORY INFORMATION WHEN A RECORD OF SURVEY IS NOT REQUIRED, PER RCW 58.09.040(2). (UPDATED 8/01/2019. DO NOT REVISE THIS FORM)

Jammana Jammana CERTIFICATE: THIS LAND CORNER RECORD CORRECTLY REPRESENTS WORK PERFORMED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE SURVEY RECORDING ACT. GRANTOR: Erielle Lamb SEAL/SIGNATURE/DATE SIGNATURE: **CERTIFICATE NO.:** 20100531 ADDRESS: 987 McClellan Rd 2010053 SUR N. Sol Vancouver, WA 98661 LAND **GRANTEE: PUBLIC** TWP: 4N RGE: 5E SEC: 7 & 18 INDEXING INFORMATION: 1/4___ CORNER CODE, SEE DIAGRAM BELOW: ADDITIONAL IDENTIFIER: (PLSS CORNER NAME) Closing Corner of S7 & S18 Only 1194534 **WPCS:** N: 189038 DATE OF OBSERVATION: 3/6/2025 ZONE: WA South NAD83(2011) BLM GCDB POINT IDENTIFIER (OPTIONAL): 100500

PROVIDE THE **FOLLOWING INFORMATION ON** ATTACHMENTS, AS **REQUIRED BY** RCW 58.09.060(2)

(a) AN ACCURATE DESCRIPTION AND LOCATION, IN REFERENCE TO THE CORNER POSITION, OF ALL MONUMENTS AND ACCESSORIES FOUND AT THE CORNER; (b) AN ACCURATE DESCRIPTION AND LOCATION, IN REFERENCE TO THE CORNER POSITION, OF ALL MONUMENTS AND ACCESSORIES PLACED OR REPLACED AT THE CORNER; (c) BASIS OF BEARINGS USED TO DESCRIBE OR LOCATE SUCH MONUMENTS OR ACCESSORIES; (d) COROLLARY INFORMATION THAT MAY BE HELPFUL TO RELOCATE OR IDENTIFY THE CORNER. POSITION.



PAGE 1 OF 3

LAND CORNER RECORD ATTACHMENT

CORNER INFORMATION: DISCUSS THE HISTORY, EVIDENCE FOUND, AND PERPETUATION OF THE CORNER. SHOW THE REFERENCES; PROVIDE THE DATE OF THE FIELD WORK; IF APPLICABLE, MAKE REFERENCE TO A MAP OF RECORD AND/OR THE FIELD BOOK/PAGE NO. USE ADDITIONAL SHEETS AS NEEDED.

History:

(1897) Christian Anderson, under contract #503 with the Government Land Office, set a fir post, 3 feet long, 4 inches square, 24 inches in the ground, marked "CC T4N R5E" on the East, "S7" and 2 grooves on the North, and "S18" and 4 grooves on the South. The following references were taken: A 24" fir, N65°E, 45 links distance, marked "T4N R5E S7 BT" A 55" fir, S65°E, 33 links distance, marked "T4N R5E S18 BT"

(1983) Corner recovered by Licensed Surveyor A.B. Carpenter, with Weyerhaeuser, in August 1983. Found 1 inch iron pipe and 3"x3" cedar post as set in 1934. Set a 2-1/2 inch aluminum monument, at iron pipe positions, marked "LS16196 T4N S12 R4E T4N S7 CC S18 R5E 1983". The following references were found:

A 55" fir stump, S65°E, 20.4' distance to center, no marks
A 24" fir snag, N61°E, 27.7' distance to center, marked "T4N R4E S7 GLO
BT"

From the aluminum monument the following references were taken: An 8" fir, S48°E, 21.50' distance, scribed "T4N R5E S18 BT", with galvanized nail, Weyerhaeuser reference plate on front and Land Survey Monument sign on back.

Evidence:

(2025) R. Ellis, of USDA Forest Service, Columbia Land Zone, on 3/6/2025, recovered corner monument. Found 2-1/2 inch aluminum cap, on a 2 inch pipe, 8 inches above ground, as set in 1983. The following references were found:

A 26" doug fir, S48°E, 21.5' distance, with healed blaze A dead and rotting stump, N61°E, 27.7' distance, with visible scribing

Perpetuation:

Set a 5/8 inch rebar, 24 inches long, with a pink plastic cap, "WA PLS 20100531", flush with ground, N20°E, 3' distance. Placed a guard post with Land Survey Monument sign and Bearing Tree tag attached, behind rebar.

NOTE: This corner is junior to corners set in T4N R4E and was established with a tie in one direction only and set at record bearing (See "2009 Manual of Surveying Instructions", 7-45). US Forest Service posted boundary does not hold this corner for the Township boundary.

