SHORE PLAT APPLICATION

HAME Bill Boy	x d	(Home) Phone (Business)	116-885-6678
ADDRESS R+2 13 Property to be divided Location: Sec. //	0x 2499 Aut	Lunu C2.	95603 1-5-11-8-300
Water Supply Source:	Spring Son	Vago Disposal Mail	od: Reptie
By one Applicant: I h	Proper y: 7~/~/ ereby certify the lots intended for:		·· ·····
Home on	lots 102 Jo	11	
	b. Kept in fam		-
	,	/	
Signature of Applicant	- Bise IL Be	Dates	-30 29

LEGAL DESCRIPTION: Describe entire contiguous ownership. Una extra sheets if required.

Beginning at a point on the north boundary of Riverside Drive, said point of beginning being 1743.0 feet south and 2750.9 west of the Northeast Corner of Section 11, T. 1 N., R. 5 E., W.M., Skamania County, Washington; thence N 44° 31' W 451.4 feet; thence, N 83° 45' W 61.8 feet; thence, N 16° 33' W 37.0 feet to the south boundary of State Highway No. 14; thence, westerly along said south highway boundary to the Northwest Corner of that tract of land conveyed to Bill V. Beard and Mildred Beard, Husband and wife, recorded in Book 70 page 297 of deed records of Skamania County; thence south 750 feet to the center of Duval Creek; thence along the center of Duval Creek N 68° 51' E 145.6 feet; thence, N 74° 55' E 280.4 feet; thence, N 72° 40' E 211.4 feet; thence S 83° 10' E 97.4 feet; thence S 41° 40' E 85.6 feet; thence S 16° 58' W 124.82; thence, leaving Duval Creek, N. 43° 07' E 104.45 to the northwesterly line of Riverside Drive; thence, N 09° 05' E 36.67 feet; thence N 05° 22' E 153.84; thence N 21° 47' E 274.54 to the point of beginning. Subject to flowage easement as granted by instrument recorded in Book Z of deed, page 581, records of Skamania County, Washington.







Southwest Washington PAGE 146 A Health District

(CLARK - KLICKITAT - SKAMANIA COUNTIES)

DONALD A. CHAMPAIGN M. D., M. P. H. / DISTRICT HEALTH OFFICER

September 27, 1979

Mr. Robert P. Lee, Director Planning Department Skamania County Stevenson, WA 98648

Re: Proposed Beard Short Plat, Tax # 1-5-11-B, 200 & 300

Dear Bob:

Site evaluations were made at one location on each of lots 2 and 3 of the above captioned short plat. Both had unsatisfactory soil conditions. This evaluation is limited to that area in the immediate vicinity of the test holes. It appears that there may not be a buildable site on these two lots.

I recommend that the short plat be approved with that word of caution attached.

Sincerely,


Don Hogarty, R. J.

Don Hogarty, R.S. Public Health Sanitarian

DH:je

cc Victor L. Beard George W. Gardner

WHITE SALMON OFFICE—130 JEWETT—WHITE SALMON, WASHINGTON 98672—TELEPHONE 493-1558



R. P. Lee

7-30-79

agency arising

12-10-79

County Auditor