

INTERNATIONAL PAPER CO.
ENGINEERING OFFICE

P. O. BOX 67 - AMBOY, WASHINGTON 98601 - PHONE (206) 247-5411

BOOK 9/6 PAGE 1

93074

LAND CORNER RECORD

Skamania

County

T 9 N R 6E W.M.

Corner Code No. J--7

Segregated Surveys:

Name: 1 Corner Sections 8 & 17

Corner No.

OLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

Corner established in 1903 and remonumented in 1915. 3/4" iron pipe set from BT by International Paper in 1972.


2. Description of Evidence Found:

Found 3/4" iron pipe and one TB - 30" hemlock stump BRS. S35°45'W 9.9' with visible scribe.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. Page No.

Date of work 8/81

Set 2" x 30" galvanized iron pipe with brass cap stamped:



Re-referenced as follows:

12" x 40" high silver fir snag BRS N16E 12.1' to nail in axed face. Tagged.

Washington Plane Coordinates: N/A Zone, Y X

Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at:

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date Sept 15, 1981

Frank M. Rumphrey L.S. 15669
Signature Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this 15th day of September, 1981 at 1:30 P.M.
In Book 9/6 of Measurements at page 1 at the request
of John Thaler for International Paper Co.

Deci M. Mearns by B. Babcock
County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.