

94710

## LAND CORNER RECORD

T. 7 N. R. 6E W.M. Skamania County  
 Segregated Surveys: Corner Code No. J-13  
 Name: Section corner Corner No.:  
 DLC, RES. Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

## 1. History of Corner Establishment and Subsequent Restoration:

This corner was originally set by Deputy Lewis D.W. Shelton in July 1899, & Oct.-Dec. 1900 under Contract No. 552. Remonumented by Floyd A. Brooks, Cadastral Surveyor in Oct. & Nov. 1961.

Set Cedar post.

Scribed 30" Cedar N49 1/2 E-46 lks..

16" Wh. Fir S65 3/4 E-34 lks..

10" Wh. Fir S29 W-29 lks..

40" Cedar N63 W-9 lks..

Set concrete post with Brass cap.

Scribed 9" Wh. Fir N68 1/2 E-38 1/2 lks..

8" Wh. Fir S82 1/2 E-46 lks..

8" Hemlock N3 W-37 lks..

## 2. Description of Evidence Found:

Shattered remains of BLM concrete post-the Brass cap is gone.

Orig. 10" now 24" sawed Wh. Fir stump S29 W-29 lks. healed blaze.

Orig. 40" now 40" Cedar sawed stump N63 W-9 lks. scribing visible on partially healed blaze.

## 3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 6 Page No. 7 Date of work July 1982

Set 2 1/2"x30" Aluminum pipe with a 2 1/2" Aluminum cap. Buried remains of concrete post in hole next to monument set. Marked:

New Bearing Trees:

6" Alder N65 W, 29.0 ft. bark scribed T7NR6ES9BT and with a 3/4" Brass disk stamped PLS 16337.

6" D-Fir N48 E, 44.1 ft. scribed T7NR6ES10 upper blaze and a lower blaze scribed BT and with a 3/4" Brass disk stamped PLS 16337.

6" Alder S89 E, 36.9 ft. bark scribed T7NR6ES15BT and with a 3/4" Brass disk stamped PLS 16337.

10" Hemlock S17 W, 97.0 ft. scribed T7NR6ES16 upper blaze and a lower blaze scribed BT and with a 3/4" Brass disk stamped PLS 16337.

Nailed 54-4 and BT signs to BT's and painted band and blazes red.

Set guard posts North and East with sign 54-4 and BM 102 decal.

T. 7N R. 6E

S9 S10

S16 S15

1982

PLS 16337

Washington Plane Coordinates: Zone Y  
 Order Accuracy. Derived From: X

Pin Pointed on Photo No. Date Located at

## SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date July 4, 1982

Signature

Larry D. Bishop

16337

Certificate No.

[SEAL]



## AUDITOR'S CERTIFICATE

Filed for record this 14 day of Sept 1982 at 1:30 P.M. In Book 16 of Monument at page 28 at the request of

Larry D. Bishop  
 County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.