

94741

LAND CORNER RECORD

T. N., R. 6E, S. 32, W.M. Shamania County A-17
 Segregated Surveys: Corner Code No. A-17
 Name: Section Corner Corner No.
 DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite

1. History of Corner Establishment and Subsequent Restoration:

This corner was originally set by Deputy Lewis B.M. Shelton in July 1899, & Oct.-Dec. 1900 under Contract No. 552.
 Set Cedar post.
 Scribbled 20" Fir N733/4E-10 lks..
 18" Fir S333/4E-12 lks..
 12" Fir S223/4E-29 lks..
 12" Fir N267/4E-12 lks..
 Remonumented by Floyd A. Brooks, Cadastral Surveyor in Oct. & Nov. 1964.
 Set iron post with Brass cap.
 Scribbled 5" Hemlock N267-38 1/2 lks..

2. Description of Evidence Found:

BM. Iron post with Brass cap.
 Orig. 20" now 33" sawed Fir stump N733/4E-10 lks.-healed blaze.
 Orig. 18" now 26" sawed Fir stump S333/4E-12 lks.-healed blaze.
 Orig. 12" now 20" sawed Fir stump S223/4E-29 lks.-healed blaze.
 Orig. 12" now 20" broken Fir snag N267-10 lks.-nearly healed blaze.
 Brooks 5" now 3" Hemlock N267-38 1/2 lks.-healed blaze.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 6 Page No. 2 Date of work July 1982

Not Bearing Trees:

6" Fir N132, 10.1 ft. scribed N733/4E upper blaze and a lower blaze scribed
 BT and with a 3/4" Brass disk stamped PLS 1633.
 13" Hemlock S332, 11.5 ft. scribed S333/4E upper blaze and a lower blaze scribed
 BT and with a 3/4" Brass disk stamped PLS 1633.
 6" Hemlock S432, 6.1 ft. scribed S223/4E upper blaze and a lower blaze scribed
 BT and with a 3/4" Brass disk stamped PLS 1633.
 Set guard post Northeast with sign 34-4 only.
 Nailed 34-4 and BT signs to all BT's and painted band and blazes red.

Washington Plane Coordinates: Zone: Y X
 Order Accuracy. Derived From:
 Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date July 30, 1982

Signature

Larry D. Bishop16337
Certificate No.

AUDITOR'S CERTIFICATE

Filed for record this 14 day of Sept 1982 at 1:30 P.M. In Book 76 of Monumental at page 29 at the request of

Larry D. Bishop
Shirley M. Olson
 County Auditor