

94746

LAND CORNER RECORD

T. 7 N. R. 6E, W.M. Skamania County
 Segregated Surveys: Corner Code No. E-15
 Name: One-quarter corner Corner No.:
 D.L.C. RES. Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

This corner was originally set by Deputy Lewis D.W. Shelton in July 1899, & Oct.-Dec. 1900 under Contract No. 552. Remonumented by Floyd A. Brooks, Cadastral Surveyor in Oct. & Nov. 1961.
 Set Wh. Fir post. Set iron post with Brass cap.
 Scribed 24" Wh. Fir N6E-15 lks.. Found unrecorded Wh. Fir 23"
 7" Wh. Fir S16 1/2 W-7 lks.. S62E-39 lks..
 Scribed 5" Wh. Fir N9E-29 lks..

2. Description of Evidence Found:

BLM monument destroyed by fire trail construction.
 Orig. 24" now 30" Wh. Fir stump scribing visible N6E-15 lks..
 Unrecorded: Now 28" Noble Fir windfall healed blaze S62E-49 lks..

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 8. Page No. 4. Date of work July 1982

Set 2 1/2"x30" Aluminum pipe with a 2 1/2" Aluminum cap 24" in ground. Marked:

New Bearing Trees:

11" Wh. Fir N74W, 31.6 ft. scribed 1/8 S3 upper blaze
 and a lower blaze scribed BT and with a 3/4"
 Brass disk stamped PLS 16337.
 12" Cedar S5W, 29.0 ft. scribed 1/8 S10 upper blaze
 and a lower blaze scribed BT and with a 3/4"
 Brass disk stamped PLS 16337.

T. 7N R. 6E
 S3
 1/8 S10
 1982
 PLS 16337

Set guard post with sign 54-4 and BM 102 Secal East.
 Painted red band and blazes red on BT's, nailed signs 54-4 and BT signs on BT's.

Washington Plane Coordinates: Zone, Y, X
 Order Accuracy. Derived From:
 Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date AUG 4, 1982
 Signature Larry D. Bishop Certificate No. 16337

AUDITOR'S CERTIFICATE

Filed for record this 4 day of Sept 1982 at 1:30 P. M. In
 Book 7/6 of Monuments at page 34 at the request of
 Larry D. Bishop
 County Auditor