

95284

LAND CORNER RECORD

SKAMANIA

County

T. 4 N. R. 9 E. W.M.

Corner Code No. U-17

Segregated Survey

Merial. SOUTH 1116

Corner No.

D.C., H.S., T.M., Mining Claims, Indian Allotment, Federal Reserve, Townsite.




1. History of Corner Establishment and Subsequent Restoration:

OLSEN ENGINEERING SET CORNER
IN 1971

2. Description of Evidence Found:

FOUND ABOVE MENTIONED CORNER (A 3/8" x 30" I.R.)
BEARING N. 88° W. A DISTANCE OF 1.99 FEET FROM
OUR SET POINT.

3. Describe Monument, Accessories and Ceryory Data to Perpetuate this Corner Location. Diagram corner and indicate monument and reference to map of record. Surveyor's Field Book No. 6 Page No. 9 Date of work 12/82

SET A 2 1/2" x 30" ALUM. PIPE WITH
A 2 1/2" ALUM. CAP.

Washington Plane Coordinates

Zone, Y

X

Order Accuracy, Decl. of Mount.

By Definition Plate No.

Date

Located at


SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or
under my direction in compliance with the provisions of Chapter
50, Laws of 1973, Title 1-6-1983

Royso G. Gaylor

Certificate No.

95284



AUDITOR'S CERTIFICATE

Filed for record this 14th day of January 1983 at 10:40 A. M. in
Book 4/9 of Monuments at page 24 at the request of

Perra Surveying

Gary M. Olson by B. Babcock
County AuditorForm prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2),
Chapter 50, Laws of 1973.