

97814

2/10 PAGE 41

T. N. TRANTOW SURVEYING

P.O. Box 287
Bingen, Washington 98605

LAND CORNER RECORD

SKAMANIA County

T. 3 N, R. 10 E, W.M.

Corner Code No. M-13

Segregated Surveys:

Name: S 1/16 corner between Sections 15 & 16

Corner No.:

DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

Point established c. 1971 by Clark Eldridge, using a proportioned position for the $\frac{1}{4}$ corner to the north. The $\frac{1}{4}$ corner was recovered in 1981, and this 1/16 corner is no longer valid. Property descriptions based on this corner have been corrected to reflect the new corner set.

2. Description of Evidence Found:

Found 3/4" iron pipe, and nearby property corners (128 ft. South, 70 ft. North), all not accepted. Set new 1/16 corner at the proper position.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 31015-1, Page No. 39, Date of work July 19, 1983.

Set a $\frac{1}{2}$ x 30" iron rod with plastic plug flush with the pavement of Lacock-Kelchner Road.

No references convenient to mark, but nearby property corners set with a similar monument bear:

NE Corner of Tax Lot 1590, N $0^{\circ}28'42''$ E, 70.00 feet
SE Corner of Tax Lot 1590, S $0^{\circ}28'42''$ W, 128.00 feet

Washington Plane Coordinates: South Zone, Y 151103.03, X 1732630.25
third Order Accuracy. Derived From: DNR "Underwood" survey of 1982.

Pin Pointed on Photo No. Date Located at.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 22 July 1983.

Signature

15673

Certificate No.

97814

AUDITOR'S CERTIFICATE

Filed for record this 28th day of June 1984 at 4:50 P. M. In Book 3/10 of Monuments at page 41 at the request of TRANTOW SURVEYING.

County Auditor