




THE WEST 1/4 CORNER AND SOUTHWEST SECTION CORNER ARE WELL ESTABLISHED. WE WERE UNABLE TO DETERMINE A REASON FOR THE DIFFERENCE BETWEEN THE WEST SECTION LINE AND THE EXISTING FENCE LOCATION. WE REFERENCED AND MADE USE OF PLS 9579, PROJECT # 76-56.



SW 1/4, SW 1/4, SECTION 33,
T.2N., R.6E., W.M.

- SET 5/8" x 30" IR.
- FOUND MONUMENT of RECORD
- CALCULATED, NOT SET
- ++ POSTED LINE

DATE: MARCH 1986
SCALE: 1" = 300'
PROJECT: 8110
P.O. Box 617, Hood River, OREGON
(503) 386-4531 97031

(SIGNED AND SEALED) 
 CERTIFICATE NUMBER 1873

AUDITOR'S CERTIFICATE

FILED FOR RECORD THIS 25 DAY OF April
19 86 AT 11:50 M. IN BOOK 3 OF Surveys
AT PAGE 237 AT THE REQUEST OF Ray O. Layland
(SIGNED) Larry M. Olson
COUNTY AUDITOR

SURVEY
for
MRS. MELVIN ENGEL
SKAMANIA, WASHINGTON