



107733

BOOK 6/6 PAGE 4/1

## LAND CORNER RECORD

HAMPSTUR CORPORATION  
1010 Douglas A3  
LONGVIEW, WASHINGTON 98632

T 6 N.R. 6 E. WM

SKAMANIA

County

Segregated Surveys:

Corner Code No. A-3

Name: N. 1/4 corner of Section 6

Corner No.:

DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

## 1. History of Corner Establishment and Subsequent Restoration.

This corner was originally established in 1900, by Lewis Shelton under GLO contract #552. It was then remonumented with a 1"x36" iron pipe and brass cap by Chester Pecore, while working under GLO contract, group #19. The D.N.R. then replaced the original pipe with a concrete mon. in 1987 and buried the pipe next to the new mon., as shown in the diagram below. Then on July 28, 1988, R. Bogdon (from HAMPSTUR CORP.), located the above corner and refreshed the RP's and set a steel reference post, as shown below, while working on a "corner restoration" project for PLUM CREEK TIMBER COMPANY, under the direction of C. Hampton, PLS #18,087.

## 2. Description of Evidence Found:

1921 ORIGINAL GLO MONUMENT: found buried next to the DNR monument set in 1987.

ORIGINAL (1921) BI'S:

-10" Fir, N02°E--11 lks.; fd. a 10" stump, 1 ft. tall with "BI tag"

-10" Fir, S064°E--12 lks.; fd. a 14" stump, 1 ft. tall with "BI tag"

SUBSEQUENT RESTORATION:

Found the "DNR-mon." as shown in the diagram below along with 4 RP's also shown in the diagram below.

## 3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. PS-056 Page No. 27-28 Date of work 7-28-88

## LOCATION:

- on a flat area, 25 ft. North of a 25% South slope.
- approx. 165 ft. South of an old E-W cutting line.
- in approx. 4 yr. old reprod.
- approx. 580 ft. West of the SW corner of an existing stand of mature Fir.
- 135 ft. North of road #1060, which bears S86°W--N86°E; at a point which is 590 ft. Westerly of a culvert under the road at a switch-back.
- 75 ft. East of "PI" on spur road, which bears North-South.
- set a 4"x4"x8" treated post with location tag on North edge of road, tag reads "North-119"

Washington Plane Coordinates:

Zone, Y

Order Accuracy. Derived From:

Pin Pointed on Photo No.

Date

Located at

## SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date August 28, 1989

Signature

Calvin J. Hampton, PLS

LS #18,087

Certificate No.



## AUDITOR'S CERTIFICATE

Filed for record this day of 19 at M. In Book of at page at the request of

County Auditor

Form presented by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.

Filed 9-1-89  
by [signature]  
[initials]