

10-28-86

Laird
Bressler

52

008.27

GLO Survey

S89°50'W on true line

29.00 top of ascent

40.00 Set post


24" Larch S11°15'W 113L. 74.58'

44" Hemlock N78°45'W 116L 76.56

53.00 Creek, 10 fks wide 358 from 1/4

1/4 corner $\frac{10}{15}$ T3N R6E

Found: 44" hemlock snag @ N79W, 76.6'
 3 Roots protruding from beneath
 2 large windfalls. It appears
 one of these windfalls fell over
 the BT, knocking it over.



Set DNR film mon @ GLO distance
 and bearing from 44" hemlock B.

BOOK 3/4 PAGE 41